

Submittal Summary - Scaffold - Remediation Phase Week 46 (03/10/08 to 03/16/08)

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 2.5 (ug/m ³)	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
							40			
							65			

RESULTS PENDING

Submittal Summary - Scaffold - Remediation Phase Week 46 (03/10/08 to 03/16/08)

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 10 (ug/m ³)	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
							150			
							150			

RESULTS PENDING

Submittal Summary - Scaffold - Remediation Phase Week 46 (03/10/08 to 03/16/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Mercury-Total Concentration (ng/m ³)	Unit	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
											300					
											3,000					
Target Air Quality Levels																
EPA Site Specific Trigger Levels																
BRL	FH-031008-11	#1 - Sidewalk bridge level NW corner	03/10/2008	Scaffold	0.5752	0811021-01	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-12	#2 - Sidewalk bridge level SW corner	03/10/2008	Scaffold	0.5764	0811021-02	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-13	#3 - Sidewalk bridge level SE corner	03/10/2008	Scaffold	0.5764	0811021-03	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-14	#4 - Sidewalk bridge level NE corner	03/10/2008	Scaffold	0.5768	0811021-04	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-15	#5 - 5th floor setback roof N side	03/10/2008	Scaffold	0.5768	0811021-05	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-16	#6 - 5th floor setback roof SW side	03/10/2008	Scaffold	0.5772	0811021-06	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-17	#7 - 5th floor scaffold at SE corner	03/10/2008	Scaffold	0.5768	0811021-07	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	
BRL	FH-031008-18	#8 - 5th floor scaffold at NE corner	03/10/2008	Scaffold	0.5772	0811021-08	03/12/2008	03/14/2008	EPA 324/1631	Hg	<26	ng/m ³	03/17/2008	No	No	

RESULTS PENDING

Submittal Summary - Scaffold - Remediation Phase Week 46 (03/10/08 to 03/16/08)

Lab Name	Field Sample ID	Sample Location	Date Collected	Project Phase	Sample Volume (m3)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Unit	Flag	Qualifier	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments									
Target Air Quality Levels										5,000	5,000	20	50	600	10,000	1,500	500	200	16,000																
EPA Site Specific Trigger Levels										14,000	5,000	200	100,000	5,000	20,000	3,000	1,000	200,000																	
STL-SAC	FH-031008-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	3/10/2008	Scaffold	5.752	GRC120187001	3/12/2008	3/13/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<86.9	<17.4	<86.9	<86.7	<86.7	<348	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	3/10/2008	Scaffold	5.764	GRC120187002	3/12/2008	3/13/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	3/10/2008	Scaffold	5.764	GRC120187003	3/12/2008	3/13/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	3/10/2008	Scaffold	5.768	GRC120187004	3/12/2008	3/13/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	3/10/2008	Scaffold	5.768	GRC120187005	3/12/2008	3/13/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	3/10/2008	Scaffold	5.772	GRC120187006	3/12/2008	3/13/2008	6020	<34.6	<1730	<17.3	<17.3	<173	<86.6	<17.3	<86.6	<86.6	<86.6	<346	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	3/10/2008	Scaffold	5.768	GRC120187007	3/12/2008	3/13/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031008-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	3/10/2008	Scaffold	5.772	GRC120187008	3/12/2008	3/13/2008	6020	<34.6	<1730	<17.3	<17.3	<173	<86.6	<17.3	<86.6	<86.6	<86.6	<346	ng/m3			3/17/2008	No	No									
STL-SAC	FH-031108-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	3/11/2008	Scaffold	5.764	GRC130213001	3/13/2008	3/17/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031108-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	3/11/2008	Scaffold	5.772	GRC130213002	3/13/2008	3/17/2008	6020	<34.6	<1730	<17.3	<17.3	<173	<86.6	<17.3	<86.6	<86.6	<86.6	<346	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031108-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	3/11/2008	Scaffold	5.768	GRC130213003	3/13/2008	3/17/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031108-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	3/11/2008	Scaffold	5.756	GRC130213004	3/13/2008	3/17/2008	6020	<34.7	<1740	<17.4	<17.4	<174	<86.9	<17.4	<86.9	<86.9	<347	ng/m3			3/18/2008	No	No										
STL-SAC	FH-031108-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	3/11/2008	Scaffold	5.756	GRC130213005	3/13/2008	3/17/2008	6020	<34.7	<1740	<17.4	<17.4	<174	<86.9	<17.4	<86.9	<86.9	<347	ng/m3			3/18/2008	No	No										
STL-SAC	FH-031108-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	3/11/2008	Scaffold	5.764	GRC130213006	3/13/2008	3/17/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031108-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	3/11/2008	Scaffold	5.76	GRC130213007	3/13/2008	3/17/2008	6020	<34.7	<1740	<17.4	<17.4	<174	<86.8	<17.4	<86.8	<86.8	<86.8	<347	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031108-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	3/11/2008	Scaffold	5.756	GRC130213008	3/13/2008	3/17/2008	6020	<34.7	<1740	<17.4	<17.4	<174	<86.8	<17.4	<86.8	<86.8	<86.8	<347	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031108-67	DUPLICATE (STATION #1)	3/11/2008	Scaffold	5.764	GRC130213010	3/13/2008	3/17/2008	6020	<34.7	<1730	<17.3	<17.3	<173	<86.7	<17.3	<86.7	<86.7	<86.7	<347	ng/m3			3/18/2008	No	No									
STL-SAC	FH-031208-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	3/12/2008	Remediation	5.76	GRC140342001	3/14/2008	3/17/2008	6020	<34.7	<1740	<17.4	<17.4	<174	<86.8	<17.4	<86.8	<86.8	<86.8	<347	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	3/12/2008	Remediation	5.74	GRC140342002	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<87.1	<17.4	<87.1	<87.1	<87.1	<348	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	3/12/2008	Remediation	5.744	GRC140342003	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<87.0	<17.4	<87.0	<87.0	<87.0	<348	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	3/12/2008	Remediation	5.752	GRC140342004	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<86.9	<17.4	<86.9	<86.9	<86.9	<348	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	3/12/2008	Remediation	5.752	GRC140342005	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<86.9	<17.4	<86.9	<86.9	<86.9	<348	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	3/12/2008	Remediation	5.74	GRC140342006	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<87.1	<17.4	<87.1	<87.1	<87.1	<348	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	3/12/2008	Remediation	5.748	GRC140342007	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<87.0	<17.4	<87.0	<87.0	<87.0	<348	ng/m3			3/19/2008	No	No									
STL-SAC	FH-031208-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	3/12/2008	Remediation	5.748	GRC140342008	3/14/2008	3/17/2008	6020	<34.8	<1740	<17.4	<17.4	<174	<87.0	<17.4	<87.0	<87.0	<87.0	<348	ng/m3			3/19/2008	No	No									

Submittal Summary - Scaffold - Remediation Phase Week 46 (03/10/08 to 03/16/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Silica-Quartz Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											10				
EPA Site Specific Trigger Levels											10				
EMSL	FH-031008-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/10/2008	Scaffold	2.876	040805728-0001	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/13/2008	No	No	
EMSL	FH-031008-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/10/2008	Scaffold	2.882	040805728-0002	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/13/2008	No	No	
EMSL	FH-031008-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/10/2008	Scaffold	2.882	040805728-0003	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	<7	03/13/2008	No	No	See Note 1
EMSL	FH-031008-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/10/2008	Scaffold	2.884	040805728-0004	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/13/2008	No	No	
EMSL	FH-031008-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/10/2008	Scaffold	2.884	040805728-0005	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/13/2008	No	No	
EMSL	FH-031008-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/10/2008	Scaffold	2.886	040805728-0006	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/13/2008	No	No	
EMSL	FH-031008-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/10/2008	Scaffold	2.884	040805728-0007	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/13/2008	No	No	
EMSL	FH-031008-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/10/2008	Scaffold	2.886	040805728-0008	03/12/2008	03/12/2008	NIOSH 7500 XRD	Silica-Quartz	6	03/13/2008	No	No	
EMSL	FH-031108-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/11/2008	Scaffold	2.882	040805830-0001	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/14/2008	No	No	
EMSL	FH-031108-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/11/2008	Scaffold	2.882	040805830-0002	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/14/2008	No	No	
EMSL	FH-031108-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/11/2008	Scaffold	2.886	040805830-0003	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	7	03/14/2008	No	No	
EMSL	FH-031108-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/11/2008	Scaffold	2.884	040805830-0004	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/14/2008	No	No	
EMSL	FH-031108-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/11/2008	Scaffold	2.878	040805830-0005	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/14/2008	No	No	
EMSL	FH-031108-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/11/2008	Scaffold	2.878	040805830-0006	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/14/2008	No	No	
EMSL	FH-031108-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/11/2008	Scaffold	2.882	040805830-0007	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/14/2008	No	No	
EMSL	FH-031108-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/11/2008	Scaffold	2.878	040805830-0008	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	5	03/14/2008	No	No	
EMSL	FH-031108-68	DUPLICATE (STATION #1)	03/11/2008	Scaffold	2.882	040805830-0010	03/12/2008	03/14/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/14/2008	No	No	
EMSL	FH-031208-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/12/2008	Remediation	2.880	040805958-0001	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	4	03/17/2008	No	No	
EMSL	FH-031208-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/12/2008	Remediation	2.870	040805958-0002	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/17/2008	No	No	
EMSL	FH-031208-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/12/2008	Remediation	2.872	040805958-0003	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	5	03/17/2008	No	No	
EMSL	FH-031208-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/12/2008	Remediation	2.876	040805958-0004	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/17/2008	No	No	
EMSL	FH-031208-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/12/2008	Remediation	2.878	040805958-0005	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/17/2008	No	No	
EMSL	FH-031208-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/12/2008	Remediation	2.870	040805958-0006	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/17/2008	No	No	
EMSL	FH-031208-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/12/2008	Remediation	2.874	040805958-0007	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/17/2008	No	No	
EMSL	FH-031208-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/12/2008	Remediation	2.874	040805958-0008	03/14/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/17/2008	No	No	
EMSL	FH-031308-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/13/2008	Remediation	2.882	040806070-0001	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031308-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/13/2008	Remediation	2.880	040806070-0002	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/18/2008	No	No	
EMSL	FH-031308-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/13/2008	Remediation	2.882	040806070-0003	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031308-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/13/2008	Remediation	2.880	040806070-0004	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/18/2008	No	No	
EMSL	FH-031308-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/13/2008	Remediation	2.880	040806070-0005	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031308-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/13/2008	Remediation	2.884	040806070-0006	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031308-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/13/2008	Remediation	2.884	040806070-0007	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/18/2008	No	No	
EMSL	FH-031308-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/13/2008	Remediation	2.884	040806070-0008	03/15/2008	03/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/18/2008	No	No	
EMSL	FH-031408-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/14/2008	Remediation	2.880	040806196-0001	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/19/2008	No	No	
EMSL	FH-031408-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/14/2008	Remediation	2.880	040806196-0002	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/19/2008	No	No	
EMSL	FH-031408-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/14/2008	Remediation	2.880	040806196-0003	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	9	03/19/2008	No	No	
EMSL	FH-031408-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/14/2008	Remediation	2.880	040806196-0004	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/19/2008	No	No	
EMSL	FH-031408-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/14/2008	Remediation	2.880	040806196-0005	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/19/2008	No	No	
EMSL	FH-031408-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/14/2008	Remediation	2.880	040806196-0006	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/19/2008	No	No	
EMSL	FH-031408-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/14/2008	Remediation	2.880	040806196-0007	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/19/2008	No	No	
EMSL	FH-031408-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/14/2008	Remediation	2.880	040806196-0008	03/17/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/19/2008	No	No	
EMSL	FH-031508-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/15/2008	Remediation	2.878	040806195-0001	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031508-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/15/2008	Remediation	2.878	040806195-0002	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/18/2008	No	No	
EMSL	FH-031508-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/15/2008	Remediation	2.876	040806195-0003	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	8	03/18/2008	No	No	
EMSL	FH-031508-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/15/2008	Remediation	2.878	040806195-0004	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	3	03/18/2008	No	No	
EMSL	FH-031508-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/15/2008	Remediation	2.880	040806195-0005	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031508-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/15/2008	Remediation	2.880	040806195-0006	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031508-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/15/2008	Remediation	2.878	040806195-0007	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	6	03/18/2008	No	No	
EMSL	FH-031508-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/15/2008	Remediation	2.880	040806195-0008	03/17/2008	03/18/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/18/2008	No	No	
EMSL	FH-031608-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	03/15/2008	Remediation	2.884	040806241-0001	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/20/2008	No	No	
EMSL	FH-031608-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	03/15/2008	Remediation	2.884	040806241-0002	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/20/2008	No	No	
EMSL	FH-031608-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	03/15/2008	Remediation	2.884	040806241-0003	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	5	03/20/2008	No	No	
EMSL	FH-031608-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	03/15/2008	Remediation	2.882	040806241-0004	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/20/2008	No	No	
EMSL	FH-031608-33	#5 - 5TH FL SETBACK ROOF N. SIDE	03/15/2008	Remediation	2.880	040806241-0005	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/20/2008	No	No	
EMSL	FH-031608-34	#6 - 5TH FL SETBACK ROOF SW SIDE	03/15/2008	Remediation	2.880	040806241-0006	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	2	03/20/2008	No	No	
EMSL	FH-031608-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	03/15/2008	Remediation	2.882	040806241-0007	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	4	03/20/2008	No	No	
EMSL	FH-031608-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	03/15/2008	Remediation	2.882	040806241-0008	03/18/2008	03/19/2008	NIOSH 7500 XRD	Silica-Quartz	<2	03/20/2008	No	No	

Note 1: Secondary quartz peak used for sample due to suspected primary peak interference.

Submittal Summary - Scaffold - Remediation Phase Week 46 (03/10/08 to 03/16/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Dioxin/Furans Concentration (ng/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.00025				
EPA Site Specific Trigger Levels											0.025				
STL-SAC	FH-031308-40	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	3/13/2008	Scaffold											Results Pending

