

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Asbestos PCME Concentration (f/cm ³)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels															
EPA Site Specific Trigger Levels															
0.0009															
N/A															
EMSL	2 FH-060208-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/2/2008	2/Remediation	3.228	030816889-0001	6/3/2008	6/3/2008	PCME	ASBESTOS	<0.00083	6/4/2008	No	No	
EMSL	2 FH-060208-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/2/2008	2/Remediation	3.228	030816889-0002	6/3/2008	6/3/2008	PCME	ASBESTOS	<0.00083	6/4/2008	No	No	
EMSL	2 FH-060208-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/2/2008	2/Remediation	3.222	030816889-0003	6/3/2008	6/3/2008	PCME	ASBESTOS	<0.00084	6/4/2008	No	No	
EMSL	2 FH-060208-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/2/2008	2/Remediation	3.222	030816889-0004	6/3/2008	6/3/2008	PCME	ASBESTOS	<0.00084	6/4/2008	No	No	
EMSL	2 FH-060208-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/2/2008	2/Remediation	3.228	030816889-0005	6/3/2008	6/4/2008	PCME	ASBESTOS	<0.00083	6/4/2008	No	No	
EMSL	2 FH-060208-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/2/2008	2/Remediation	3.222	030816889-0006	6/3/2008	6/4/2008	PCME	ASBESTOS	<0.00084	6/4/2008	No	No	
EMSL	2 FH-060208-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/2/2008	2/Remediation	3.222	030816889-0007	6/3/2008	6/4/2008	PCME	ASBESTOS	<0.00084	6/4/2008	No	No	
EMSL	2 FH-060208-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/2/2008	2/Remediation	3.228	030816889-0008	6/3/2008	6/4/2008	PCME	ASBESTOS	<0.00083	6/4/2008	No	No	
EMSL	2 FH-060308-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/3/2008	2/Remediation	3.240	030817040-0001	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00083	6/6/2008	No	No	
EMSL	2 FH-060308-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/3/2008	2/Remediation	3.228	030817040-0002	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00083	6/6/2008	No	No	
EMSL	2 FH-060308-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/3/2008	2/Remediation	3.222	030817040-0003	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00084	6/6/2008	No	No	
EMSL	2 FH-060308-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/3/2008	2/Remediation	3.234	030817040-0004	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00083	6/6/2008	No	No	
EMSL	2 FH-060308-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/3/2008	2/Remediation	3.234	030817040-0005	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00083	6/6/2008	No	No	
EMSL	2 FH-060308-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/3/2008	2/Remediation	3.234	030817040-0006	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00083	6/6/2008	No	No	
EMSL	2 FH-060308-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/3/2008	2/Remediation	3.216	030817040-0007	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00084	6/6/2008	No	No	
EMSL	2 FH-060308-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/3/2008	2/Remediation	3.246	030817040-0008	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060308-65	DUPLICATE (STATION # 1)	6/3/2008	2/Remediation	3.240	030817040-0008	6/4/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060408-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/4/2008	2/Remediation	3.234	030817152-0001	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060408-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/4/2008	2/Remediation	3.228	030817152-0002	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060408-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/4/2008	2/Remediation	3.222	030817152-0003	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00077	6/6/2008	No	No	
EMSL	2 FH-060408-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/4/2008	2/Remediation	3.234	030817152-0004	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060408-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/4/2008	2/Remediation	3.222	030817152-0005	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00077	6/6/2008	No	No	
EMSL	2 FH-060408-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/4/2008	2/Remediation	3.234	030817152-0006	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060408-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/4/2008	2/Remediation	3.228	030817152-0007	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060408-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/4/2008	2/Remediation	3.234	030817152-0008	6/5/2008	6/5/2008	PCME	ASBESTOS	<0.00076	6/6/2008	No	No	
EMSL	2 FH-060508-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/5/2008	2/Remediation	3.252	030817299-0001	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060508-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/5/2008	2/Remediation	3.258	030817299-0002	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060508-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/5/2008	2/Remediation	3.264	030817299-0003	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00082	6/7/2008	No	No	
EMSL	2 FH-060508-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/5/2008	2/Remediation	3.252	030817299-0004	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060508-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/5/2008	2/Remediation	3.258	030817299-0005	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060508-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/5/2008	2/Remediation	3.252	030817299-0006	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060508-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/5/2008	2/Remediation	3.258	030817299-0007	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060508-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/5/2008	2/Remediation	3.252	030817299-0008	6/6/2008	6/6/2008	PCME	ASBESTOS	<0.00083	6/7/2008	No	No	
EMSL	2 FH-060608-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/6/2008	2/Remediation	3.246	030817420-0001	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00083	6/10/2008	No	No	
EMSL	2 FH-060608-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/6/2008	2/Remediation	3.228	030817420-0002	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00083	6/10/2008	No	No	
EMSL	2 FH-060608-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/6/2008	2/Remediation	3.222	030817420-0003	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00084	6/10/2008	No	No	
EMSL	2 FH-060608-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/6/2008	2/Remediation	3.228	030817420-0004	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00083	6/10/2008	No	No	
EMSL	2 FH-060608-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/6/2008	2/Remediation	3.246	030817420-0005	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00083	6/10/2008	No	No	
EMSL	2 FH-060608-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/6/2008	2/Remediation	3.234	030817420-0006	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00083	6/10/2008	No	No	
EMSL	2 FH-060608-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/6/2008	2/Remediation	3.222	030817420-0007	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00084	6/10/2008	No	No	
EMSL	2 FH-060608-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/6/2008	2/Remediation	3.246	030817420-0008	6/7/2008	6/7/2008	PCME	ASBESTOS	<0.00083	6/10/2008	No	No	

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Airetek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Asbestos AHERA Concentration (S/mm ²)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											N/A				
EPA Site Specific Trigger Levels											70				
EMSL	2 FH-060208-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/2/2008	2/Remediation	3.228	030816889-0001	6/3/2008	6/3/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/2/2008	2/Remediation	3.228	030816889-0002	6/3/2008	6/3/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/2/2008	2/Remediation	3.222	030816889-0003	6/3/2008	6/3/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/2/2008	2/Remediation	3.222	030816889-0004	6/3/2008	6/3/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/2/2008	2/Remediation	3.228	030816889-0005	6/3/2008	6/4/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/2/2008	2/Remediation	3.222	030816889-0006	6/3/2008	6/4/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/2/2008	2/Remediation	3.222	030816889-0007	6/3/2008	6/4/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060208-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/2/2008	2/Remediation	3.228	030816889-0008	6/3/2008	6/4/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/4/2008	No	No	
EMSL	2 FH-060308-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/3/2008	2/Remediation	3.240	030817040-0001	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/3/2008	2/Remediation	3.228	030817040-0002	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/3/2008	2/Remediation	3.222	030817040-0003	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/3/2008	2/Remediation	3.234	030817040-0004	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/3/2008	2/Remediation	3.234	030817040-0005	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/3/2008	2/Remediation	3.234	030817040-0006	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/3/2008	2/Remediation	3.216	030817040-0007	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/3/2008	2/Remediation	3.246	030817040-0008	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060308-65	DUPLICATE (STATION # 1)	6/3/2008	2/Remediation	3.240	030817040-0008	6/4/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/6/2008	No	No	
EMSL	2 FH-060408-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/4/2008	2/Remediation	3.234	030817152-0001	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/4/2008	2/Remediation	3.228	030817152-0002	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/4/2008	2/Remediation	3.222	030817152-0003	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/4/2008	2/Remediation	3.234	030817152-0004	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/4/2008	2/Remediation	3.222	030817152-0005	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/4/2008	2/Remediation	3.234	030817152-0006	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/4/2008	2/Remediation	3.228	030817152-0007	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060408-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/4/2008	2/Remediation	3.234	030817152-0008	6/5/2008	6/5/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/6/2008	No	No	
EMSL	2 FH-060508-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/5/2008	2/Remediation	3.252	030817299-0001	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/5/2008	2/Remediation	3.258	030817299-0002	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/5/2008	2/Remediation	3.264	030817299-0003	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/5/2008	2/Remediation	3.252	030817299-0004	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/5/2008	2/Remediation	3.258	030817299-0005	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/5/2008	2/Remediation	3.252	030817299-0006	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/5/2008	2/Remediation	3.258	030817299-0007	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060508-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/5/2008	2/Remediation	3.252	030817299-0008	6/6/2008	6/6/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/7/2008	No	No	
EMSL	2 FH-060608-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/6/2008	2/Remediation	3.246	030817420-0001	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/6/2008	2/Remediation	3.228	030817420-0002	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/6/2008	2/Remediation	3.222	030817420-0003	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/6/2008	2/Remediation	3.228	030817420-0004	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/6/2008	2/Remediation	3.246	030817420-0005	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/6/2008	2/Remediation	3.234	030817420-0006	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/6/2008	2/Remediation	3.222	030817420-0007	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	
EMSL	2 FH-060608-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/6/2008	2/Remediation	3.246	030817420-0008	6/7/2008	6/7/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/10/2008	No	No	

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 2.5 (ug/m ³)	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments	
							40				
							65				
							EPA Site Specific Trigger Levels				
HH-060208-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	7.65	No	No		
HH-060208-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	30.69	No	No		
HH-060208-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	27.48	No	No		
HH-060208-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	7.23	No	No		
HH-060208-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	13.84	No	No		
HH-060208-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	9.13	No	No		
HH-060208-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.28	No	No		
HH-060208-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.83	No	No		
HH-060208-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/2/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	17.96	No	No	See Note 1	
HH-060308-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	16.21	No	No		
HH-060308-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	29.27	No	No		
HH-060308-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	30.85	No	No		
HH-060308-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	15.10	No	No		
HH-060308-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	19.01	No	No		
HH-060308-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	17.86	No	No		
HH-060308-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	14.43	No	No		
HH-060308-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	20.65	No	No		
HH-060308-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/3/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	30.13	No	No		
HH-060408-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	19.78	No	No		
HH-060408-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	25.34	No	No		
HH-060408-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	20.13	No	No		
HH-060408-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	31.44	No	No		
HH-060408-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	18.91	No	No		
HH-060408-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	18.25	No	No		
HH-060408-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.31	No	No		
HH-060408-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	18.83	No	No		
HH-060408-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/4/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	18.58	No	No	See Note 1	
HH-060508-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	11.19	No	No		
HH-060508-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	21.91	No	No		
HH-060508-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.44	No	No		
HH-060508-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.85	No	No		
HH-060508-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	11.13	No	No		
HH-060508-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.58	No	No		
HH-060508-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	14.38	No	No		
HH-060508-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	13.52	No	No		
HH-060508-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/5/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	7.07	No	No		
HH-060608-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	14.38	No	No		
HH-060608-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	27.20	No	No		
HH-060608-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	15.70	No	No		
HH-060608-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.28	No	No		
HH-060608-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.85	No	No		
HH-060608-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	16.05	No	No		
HH-060608-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	8.13	No	No		
HH-060608-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	13.80	No	No		
HH-060608-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/6/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	11.64	No	No		
HH-060708-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	24.56	No	No		
HH-060708-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	35.75	No	No		
HH-060708-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	35.84	No	No		
HH-060708-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	23.15	No	No		
HH-060708-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	26.08	No	No		
HH-060708-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	27.24	No	No		
HH-060708-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	17.14	No	No		
HH-060708-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	29.05	No	No		
HH-060708-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/7/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	22.85	No	No		
HH-060808-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	24.86	No	No		
HH-060808-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	24.52	No	No		
HH-060808-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	18.12	No	No		
HH-060808-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	22.86	No	No		
HH-060808-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	31.29	No	No		
HH-060808-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	28.08	No	No		
HH-060808-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	23.83	No	No		
HH-060808-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	27.76	No	No		
HH-060808-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/8/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	22.92	No	No		

Note 1: The TEOM 2.5 unit experienced battery breaker trips, thus caused partial data available on 6/2/08 and 6/04/08.

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 10 (ug/m ³)	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
							150			
							150			
							150			
FH-060208-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	15.12	No	No	
FH-060208-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	13.38	No	No	
FH-060208-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	23.33	No	No	
FH-060208-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.92	No	No	
FH-060208-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	12.88	No	No	
FH-060208-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	13.13	No	No	
FH-060208-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	20.78	No	No	
FH-060208-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	12.38	No	No	
FH-060208-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/2/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	N/A	No	No	See Note 1
FH-060308-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	14.96	No	No	
FH-060308-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.89	No	No	
FH-060308-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	40.31	No	No	
FH-060308-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.43	No	No	
FH-060308-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.16	No	No	
FH-060308-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.26	No	No	
FH-060308-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.19	No	No	
FH-060308-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.06	No	No	
FH-060308-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/3/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	18.17	No	No	See Note 1
FH-060408-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	18.78	No	No	
FH-060408-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	35.21	No	No	
FH-060408-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	33.78	No	No	
FH-060408-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.10	No	No	
FH-060408-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	35.75	No	No	
FH-060408-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	34.90	No	No	
FH-060408-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.04	No	No	
FH-060408-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	35.92	No	No	
FH-060408-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/4/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	10.60	No	No	See Note 1
FH-060508-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.81	No	No	
FH-060508-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.86	No	No	
FH-060508-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	30.05	No	No	
FH-060508-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.32	No	No	
FH-060508-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.59	No	No	
FH-060508-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.85	No	No	
FH-060508-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	18.33	No	No	
FH-060508-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.56	No	No	
FH-060508-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/5/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	19.59	No	No	
FH-060608-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	56.65	No	No	
FH-060608-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	38.29	No	No	
FH-060608-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.39	No	No	
FH-060608-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.98	No	No	
FH-060608-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	44.58	No	No	
FH-060608-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	42.49	No	No	
FH-060608-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	18.08	No	No	
FH-060608-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.52	No	No	
FH-060608-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/6/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	25.27	No	No	
FH-060708-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	20.71	No	No	
FH-060708-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	34.23	No	No	
FH-060708-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	44.31	No	No	
FH-060708-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.69	No	No	
FH-060708-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	45.93	No	No	
FH-060708-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	38.95	No	No	
FH-060708-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.18	No	No	
FH-060708-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.65	No	No	
FH-060708-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/7/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	42.84	No	No	
FH-060808-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	21.81	No	No	
FH-060808-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	58.10	No	No	
FH-060808-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	47.60	No	No	
FH-060808-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	36.59	No	No	
FH-060808-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	49.88	No	No	
FH-060808-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	55.09	No	No	
FH-060808-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.52	No	No	
FH-060808-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	23.18	No	No	
FH-060808-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/8/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	41.46	No	No	

Note 1: The TEOM 10 unit experienced battery breaker trips, thus caused no data available on 6/3/08, and partial data available on 6/3/08 and 6/04/08.

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Ohio Lumex Daily Mercury Readings
all readings are in ng/m³

Target air quality level: 300 ng/m³

USEPA site specific mercury trigger level: 3000 ng/m³

Exceedances: None
Exceedances: None

3 Site Tours Conducted per Work Shift

DATE: 6/2/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	10	11	11	9	11	9	8	9	10	11	9	9	9.75
	1200-1205	Tour 2	9	9	8	8	10	11	9	11	11	11	9	11	9.75
	1500-1505	Tour 3	8	8	8	11	12	13	11	8	9	11	11	11	10.08
5th FLOOR	0910-0915	Tour 1	9	9	9	10	11	12	13	12	11	11	12	11	10.83
	1210-1215	Tour 2	10	10	11	11	11	10	8	9	10	11	10	11	10.17
	1510-1515	Tour 3	12	12	12	11	10	12	11	8	10	9	11	10	10.67
SETBACK ROOF PERIMETER	0925-0930	Tour 1	9	13	13	13	14	13	14	13	15	8	16	13	12.83
	1225-1230	Tour 2	13	13	15	15	15	15	13	12	12	8	15	15	13.42
	1525-1530	Tour 3	14	11	11	11	11	12	16	15	15	13	11	15	13.00

DATE: 6/2/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	19	22	22	23	21	20	22	22	23	23	19	21	21.42
	2000-2005	Tour 2	20	21	20	19	23	21	22	22	21	19	19	22	20.75
	0000-0005	Tour 3	19	20	20	21	18	24	24	21	22	23	21	22	21.25
5th FLOOR	1710-1715	Tour 1	20	21	23	21	20	22	19	19	20	21	22	21	20.58
	2010-2015	Tour 2	19	20	19	19	22	22	21	21	23	23	21	23	21.08
	0010-0015	Tour 3	20	21	22	22	20	18	21	20	21	21	22	20	20.67
SETBACK ROOF PERIMETER	1725-1730	Tour 1	19	20	30	20	21	22	21	23	22	23	22	21	21.17
	2025-2030	Tour 2	20	20	20	21	22	21	22	23	21	21	22	21	21.17
	0025-0030	Tour 3	21	20	19	19	22	20	20	20	19	19	19	18	19.67

DATE: 6/3/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	18	23	17	20	17	23	19	17	21	20	19	18	19.33
	1200-1205	Tour 2	23	20	17	19	21	17	24	19	23	20	21	19	20.25
	1500-1505	Tour 3	19	23	20	18	17	19	21	20	18	21	22	22	20.00
5th FLOOR	0910-0915	Tour 1	20	19	17	18	18	21	15	23	19	20	21	19	19.17
	1210-1215	Tour 2	17	20	25	19	20	18	18	21	17	23	20	18	19.67
	1510-1515	Tour 3	19	17	22	23	20	17	20	19	21	21	23	17	19.92
SETBACK ROOF PERIMETER	0925-0930	Tour 1	19	17	19	18	23	17	20	24	22	17	19	21	19.67
	1225-1230	Tour 2	23	18	21	19	20	24	21	17	21	17	21	18	20.33
	1525-1530	Tour 3	20	23	17	20	21	23	18	20	22	17	24	19	20.42

DATE: 6/3/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	21	20	23	20	22	22	20	21	19	23	23	21	21.25
	2000-2005	Tour 2	21	19	20	20	21	21	19	23	23	23	21	20	20.92
	0000-0005	Tour 3	20	19	23	23	21	18	19	20	24	23	21	20	20.92
5th FLOOR	1710-1715	Tour 1	22	21	22	22	24	20	21	21	23	21	20	19	21.33
	2010-2015	Tour 2	19	20	18	21	20	21	21	20	20	19	21	20	20.00
	0010-0015	Tour 3	22	22	22	19	24	19	19	22	21	22	21	20	20.92
SETBACK ROOF PERIMETER	1725-1730	Tour 1	20	18	20	20	21	22	21	24	23	24	22	22	21.42
	2025-2030	Tour 2	22	21	223	23	21	21	18	19	18	21	20	21	37.33
	0025-0030	Tour 3	20	23	21	18	23	21	19	21	23	20	21	21	21.00

DATE: 6/4/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	17	22	18	20	18	244	19	21	20	17	22	20	28.58
	1200-1205	Tour 2	19	20	20	17	24	22	19	20	19	21	17	23	19.92
	1500-1505	Tour 3	20	23	21	17	19	20	22	24	19	24	22	17	20.67
5th FLOOR	0910-0915	Tour 1	18	21	24	20	17	19	19	21	25	20	17	23	20.33
	1210-1215	Tour 2	19	20	21	17	18	23	22	20	19	24	17	19	19.92
	1510-1515	Tour 3	21	22	20	17	19	23	18	24	18	17	21	18	19.83
SETBACK ROOF PERIMETER	0925-0930	Tour 1	17	20	22	21	19	18	17	23	20	19	24	18	19.83
	1225-1230	Tour 2	20	19	17	23	24	18	19	22	17	21	18	20	19.83
	1525-1530	Tour 3	19	21	24	23	17	20	18	22	23	17	19	21	20.33

DATE: 6/4/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	21	22	19	22	21	23	21	22	22	19	19	21	21.00
	2000-2005	Tour 2	20	22	19	21	23	26	22	21	19	21	23	21	21.50
	0000-0005	Tour 3	20	23	21	23	23	19	19	21	22	20	19	19	20.75
5th FLOOR	1710-1715	Tour 1	21	21	23	24	21	23	21	20	19	23	21	20	21.42
	2010-2015	Tour 2	19	17	19	21	23	21	19	20	21	20	23	19	20.17
	0010-0015	Tour 3	20	22	22	19	20	22	19	24	21	21	23	20	21.08
SETBACK ROOF PERIMETER	1725-1730	Tour 1	21	20	22	18	19	21	24	23	19	21	20	22	20.83
	2025-2030	Tour 2	20	19	21	20	23	21	18	22	22	20	22	20	20.67
	0025-0030	Tour 3	19	21	20	23	23	24	21	18	19	21	20	21	20.83

DATE: 6/5/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	19	21	17	22	18	21	20	21	19	23	17	19	19.75
	1200-1205	Tour 2	20	23	20	19	17	20	24	22	17	23	17	24	20.50
	1500-1505	Tour 3	17	20	18	22	19	17	21	19	17	20	18	23	19.25
5th FLOOR	0910-0915	Tour 1	18	22	20	17	23	19	17	24	21	20	17	21	19.92
	1210-1215	Tour 2	19	24	17	18	20	22	20	19	24	19	18	21	20.08
	1510-1515	Tour 3	17	21	19	22	24	18	17	20	23	19	17	22	19.92
SETBACK ROOF PERIMETER	0925-0930	Tour 1	23	17	18	21	19	20	19	23	20	18	19	23	20.00
	1225-1230	Tour 2	22	19	23	20	24	17	20	19	24	22	17	18	20.42
	1525-1530	Tour 3	19	22	20	17	23	19	18	20	18	24	23	17	20.00

DATE: 6/5/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	21	24	19	21	20	18	19	22	21	20	19	21	20.42
	2000-2005	Tour 2	20	18	21	21	24	20	20	19	21	18	19	19	19.83
	0000-0005	Tour 3	19	20	18	21	22	21	23	19	20	21	19	19	20.17
5th FLOOR	1710-1715	Tour 1	19	19	20	21	20	24	21	23	21	22	21	23	21.17
	2010-2015	Tour 2	18	19	19	20	22	19	21	17	18	21	20	21	19.58
	0010-0015	Tour 3	20	17	17	22	21	20	21	20	20	20	21	20	19.92
SETBACK ROOF PERIMETER	1725-1730	Tour 1	21	20	19	23	21	22	23	21	20	21	19	18	20.67
	2025-2030	Tour 2	19	19	19	20	26	24	22	23	19	19	20	22	21.00
	0025-0030	Tour 3	20	19	21	20	23	21	19	18	21	22	20	20	20.33

DATE: 6/6/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	19	21	17	24	18	17	22	19	19	23	22	17	19.83
	1200-1205	Tour 2	20	17	24	19	21	17	19	23	20	18	19	20	19.75
	1500-1505	Tour 3	21	19	17	23	24	18	22	19	17	20	22	21	20.25
5th FLOOR	0910-0915	Tour 1	19	23	18	17	20	19	23	21	18	20	22	19	19.82
	1210-1215	Tour 2	21	20	18	19	21	17	20	22	18	23	18	17	19.50
	1510-1515	Tour 3	18	21	23	17	20	19	18	20	24	22	17	20	19.92
SETBACK ROOF PERIMETER	0925-0930	Tour 1	17	20	21	19	20	24	18	23	20	17	24	19	20.17
	1225-1230	Tour 2	18	22	24	17	23	19	20	22	17	24	19	24	20.75
	1525-1530	Tour 3	17	19	24	22	19	21	18	17	24	23	19	22	20.42

DATE: 6/6/2008 2nd SHIFT

||
||
||

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Field Sample ID	Sample Location	Date Collected	Project Phase	Sample Volume (m3)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Antimony Concentration (ug/m ³)	Barium Concentration (ug/m ³)	Beryllium Concentration (ug/m ³)	Cadmium Concentration (ug/m ³)	Chromium (Total) Concentration (ug/m ³)	Copper Concentration (ug/m ³)	Lead Concentration (ug/m ³)	Manganese Concentration (ug/m ³)	Nickel Concentration (ug/m ³)	Zinc Concentration (ug/m ³)	Unit	Flag	Qualifier	Date Reported	Exceeds Target Air Quality Level?	Exceeds EPA Site Specific Trigger Level?	Comments
Target Air Quality Levels										5,000	5,000	20	50	10,000	1,000	1,000	500	200	16,000							
EPA Site Specific Trigger Levels										14,000	14,000	200	2,000	6,000	6,000	300	100	200	16,000							
STL-SAC	FH-060208-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/2/2008	Remediation	5.712	GSF04018001	6/4/2008	6/9/2008	6020	<-3.0	<-1.750	<-1.75	<-1.75	<-17.5	<-86.7	<-17.5	<-86.7	<-86.7	<-350	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/2/2008	Remediation	5.748	GSF04018002	6/4/2008	6/9/2008	6020	<-3.4	<-1.750	<-17.3	<-17.3	<-17.3	<-86.7	<-17.3	<-86.7	<-86.7	<-347	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/2/2008	Remediation	5.752	GSF04018003	6/4/2008	6/9/2008	6020	<-3.48	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-348	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/2/2008	Remediation	5.748	GSF04018004	6/4/2008	6/9/2008	6020	<-3.48	<-1.740	<-17.4	<-17.4	<-17.4	<-86.7	<-17.4	<-86.7	<-86.7	<-348	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/2/2008	Remediation	5.736	GSF04018005	6/4/2008	6/9/2008	6020	<-3.19	<-1.740	<-17.4	<-17.4	<-17.4	<-87.2	<-17.4	<-87.2	<-87.2	<-349	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/2/2008	Remediation	5.744	GSF04018006	6/4/2008	6/9/2008	6020	<-3.48	<-1.740	<-17.4	<-17.4	<-17.4	<-87.0	<-17.4	<-87.0	<-87.0	<-348	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/2/2008	Remediation	5.76	GSF04018007	6/4/2008	6/9/2008	6020	<-3.7	<-1.740	<-17.4	<-17.4	<-17.4	<-86.8	<-17.4	<-86.8	<-86.8	<-347	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060208-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/2/2008	Remediation	5.732	GSF04018008	6/4/2008	6/9/2008	6020	<-3.4	<-1.740	<-17.4	<-17.4	<-17.4	<-87.2	<-17.4	<-87.2	<-87.2	<-348	ng/m ³			6/9/2008	No	No	
STL-SAC	FH-060308-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/3/2008	Remediation	5.76	GSF05018701	6/5/2008	6/9/2008	6020	<-3.47	<-1.740	<-17.4	<-17.4	<-17.4	<-86.8	<-17.4	<-86.8	<-86.8	<-347	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/3/2008	Remediation	5.772	GSF05018702	6/5/2008	6/9/2008	6020	<-3.6	<-1.730	<-17.3	<-17.3	<-17.3	<-86.6	<-17.3	<-86.6	<-86.6	<-346	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/3/2008	Remediation	5.772	GSF05018703	6/5/2008	6/9/2008	6020	<-3.6	<-1.730	<-17.3	<-17.3	<-17.3	<-86.6	<-17.3	<-86.6	<-86.6	<-346	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/3/2008	Remediation	5.778	GSF05018704	6/5/2008	6/9/2008	6020	<-3.6	<-1.730	<-17.3	<-17.3	<-17.3	<-86.5	<-17.3	<-86.5	<-86.5	<-346	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/3/2008	Remediation	5.764	GSF05018705	6/5/2008	6/9/2008	6020	<-3.47	<-1.730	<-17.3	<-17.3	<-17.3	<-86.7	<-17.3	<-86.7	<-86.7	<-347	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/3/2008	Remediation	5.764	GSF05018706	6/5/2008	6/9/2008	6020	<-3.47	<-1.730	<-17.3	<-17.3	<-17.3	<-86.7	<-17.3	<-86.7	<-86.7	<-347	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/3/2008	Remediation	5.772	GSF05018707	6/5/2008	6/9/2008	6020	<-3.8	<-1.730	<-17.3	<-17.3	<-17.3	<-86.6	<-17.3	<-86.6	<-86.6	<-346	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/3/2008	Remediation	5.766	GSF05018708	6/5/2008	6/9/2008	6020	<-3.13	<-1.730	<-17.3	<-17.3	<-17.3	<-86.6	<-17.3	<-86.6	<-86.6	<-346	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060308-67	DUPLICATE (STATION #1)	6/3/2008	Remediation	5.76	GSF050187010	6/5/2008	6/9/2008	6020	<-3.7	<-1.740	<-17.4	<-17.4	<-17.4	<-86.8	<-17.4	<-86.8	<-86.8	<-347	ng/m ³			6/10/2008	No	No	
STL-SAC	FH-060408-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/4/2008	Remediation	5.772	GSF060159001	6/6/2008	6/9/2008	6020	<-3.6	<-1.730	<-17.3	<-17.3	<-17.3	<-86.6	<-17.3	<-86.6	<-86.6	<-346	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/4/2008	Remediation	5.752	GSF060159002	6/6/2008	6/9/2008	6020	<-3.9	<-1.740	<-17.4	<-17.4	<-17.4	<-87.2	<-17.4	<-87.2	<-87.2	<-349	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/4/2008	Remediation	5.736	GSF060159003	6/6/2008	6/9/2008	6020	<-3.9	<-1.740	<-17.4	<-17.4	<-17.4	<-87.2	<-17.4	<-87.2	<-87.2	<-349	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/4/2008	Remediation	5.744	GSF060159004	6/6/2008	6/9/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-87.0	<-17.4	<-87.0	<-87.0	<-348	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/4/2008	Remediation	5.752	GSF060159005	6/6/2008	6/9/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-348	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/4/2008	Remediation	5.748	GSF060159006	6/6/2008	6/9/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-87.0	<-17.4	<-87.0	<-87.0	<-348	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/4/2008	Remediation	5.752	GSF060159007	6/6/2008	6/9/2008	6020	<-3.9	<-1.740	<-17.4	<-17.4	<-17.4	<-87.2	<-17.4	<-87.2	<-87.2	<-349	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060408-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/4/2008	Remediation	5.76	GSF060159008	6/6/2008	6/9/2008	6020	<-3.7	<-1.740	<-17.4	<-17.4	<-17.4	<-86.8	<-17.4	<-86.8	<-86.8	<-347	ng/m ³			6/11/2008	No	No	
STL-SAC	FH-060508-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/5/2008	Remediation	5.752	GSF090158001	6/9/2008	6/11/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-348	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/5/2008	Remediation	5.768	GSF090158002	6/9/2008	6/11/2008	6020	<-3.7	<-1.730	<-17.3	<-17.3	<-17.3	<-86.7	<-17.3	<-86.7	<-86.7	<-347	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/5/2008	Remediation	5.76	GSF090158003	6/9/2008	6/11/2008	6020	<-3.7	<-1.740	<-17.4	<-17.4	<-17.4	<-86.8	<-17.4	<-86.8	<-86.8	<-347	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/5/2008	Remediation	5.756	GSF090158004	6/9/2008	6/11/2008	6020	<-3.7	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-347	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/5/2008	Remediation	5.766	GSF090158005	6/9/2008	6/11/2008	6020	<-3.4	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-347	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/5/2008	Remediation	5.756	GSF090158006	6/9/2008	6/11/2008	6020	<-3.47	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-347	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/5/2008	Remediation	5.764	GSF090158007	6/9/2008	6/11/2008	6020	<-3.7	<-1.730	<-17.3	<-17.3	<-17.3	<-86.7	<-17.3	<-86.7	<-86.7	<-347	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060508-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/5/2008	Remediation	5.752	GSF090158008	6/9/2008	6/11/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-348	ng/m ³			6/12/2008	No	No	
STL-SAC	FH-060608-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/6/2008	Remediation	5.744	GSF100161001	6/10/2008	6/11/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-87.0	<-17.4	<-87.0	<-87.0	<-348	ng/m ³			6/13/2008	No	No	
STL-SAC	FH-060608-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/6/2008	Remediation	5.752	GSF100161002	6/10/2008	6/11/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-86.9	<-17.4	<-86.9	<-86.9	<-348	ng/m ³			6/13/2008	No	No	
STL-SAC	FH-060608-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/6/2008	Remediation	5.748	GSF100161003	6/10/2008	6/11/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-87.0	<-17.4	<-87.0	<-87.0	<-348	ng/m ³			6/13/2008	No	No	
STL-SAC	FH-060608-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/6/2008	Remediation	5.748	GSF100161004	6/10/2008	6/11/2008	6020	<-3.8	<-1.740	<-17.4	<-17.4	<-17.4	<-87.0	<-17.4	<-87.0	<-87.0	<-348	ng/m ³						

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Silica-Quartz Concentration (ug/m ³)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											10				
EPA Site Specific Trigger Levels											10				
EMSL	FH-060208-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/02/2008	Remediation	2.866	040813451-0001	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	4	06/06/2008	No	No	
EMSL	FH-060208-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/02/2008	Remediation	2.882	040813451-0002	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/06/2008	No	No	
EMSL	FH-060208-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/02/2008	Remediation	2.876	040813451-0003	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	5	06/06/2008	No	No	
EMSL	FH-060208-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/02/2008	Remediation	2.874	040813451-0004	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/06/2008	No	No	
EMSL	FH-060208-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/02/2008	Remediation	2.868	040813451-0005	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	4	06/06/2008	No	No	
EMSL	FH-060208-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/02/2008	Remediation	2.872	040813451-0006	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/06/2008	No	No	
EMSL	FH-060208-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/02/2008	Remediation	2.880	040813451-0007	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/06/2008	No	No	
EMSL	FH-060208-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/02/2008	Remediation	2.866	040813451-0008	06/04/2008	06/05/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/06/2008	No	No	
EMSL	FH-060308-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/03/2008	Remediation	2.880	040813606-0001	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/06/2008	No	No	See Note 1
EMSL	FH-060308-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/03/2008	Remediation	2.886	040813606-0002	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	6	06/06/2008	No	No	
EMSL	FH-060308-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/03/2008	Remediation	2.889	040813606-0003	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	5	06/06/2008	No	No	
EMSL	FH-060308-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/03/2008	Remediation	2.884	040813606-0004	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/06/2008	No	No	
EMSL	FH-060308-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/03/2008	Remediation	2.882	040813606-0005	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/06/2008	No	No	
EMSL	FH-060308-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/03/2008	Remediation	2.882	040813606-0006	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/06/2008	No	No	
EMSL	FH-060308-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/03/2008	Remediation	2.886	040813606-0007	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/06/2008	No	No	
EMSL	FH-060308-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/03/2008	Remediation	2.878	040813606-0008	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/06/2008	No	No	See Note 1
EMSL	FH-060308-68	DUPLICATE (STATION #1)	06/03/2008	Remediation	2.880	040813606-0010	06/05/2008	06/06/2008	NIOSH 7500 XRD	Silica-Quartz	8	06/06/2008	No	No	See Note 1
EMSL	FH-060408-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/04/2008	Remediation	2.886	040813763-0001	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/09/2008	No	No	
EMSL	FH-060408-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/04/2008	Remediation	2.866	040813763-0002	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/09/2008	No	No	
EMSL	FH-060408-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/04/2008	Remediation	2.868	040813763-0003	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/09/2008	No	No	See Note 1
EMSL	FH-060408-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/04/2008	Remediation	2.872	040813763-0004	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/09/2008	No	No	
EMSL	FH-060408-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/04/2008	Remediation	2.876	040813763-0005	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/09/2008	No	No	
EMSL	FH-060408-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/04/2008	Remediation	2.874	040813763-0006	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/09/2008	No	No	
EMSL	FH-060408-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/04/2008	Remediation	2.866	040813763-0007	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/09/2008	No	No	
EMSL	FH-060408-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/04/2008	Remediation	2.880	040813763-0008	06/05/2008	06/09/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/09/2008	No	No	
EMSL	FH-060508-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/05/2008	Remediation	2.876	040813895-0001	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/12/2008	No	No	See Note 1
EMSL	FH-060508-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/05/2008	Remediation	2.884	040813895-0002	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060508-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/05/2008	Remediation	2.880	040813895-0003	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/12/2008	No	No	See Note 1
EMSL	FH-060508-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/05/2008	Remediation	2.878	040813895-0004	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060508-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/05/2008	Remediation	2.878	040813895-0005	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060508-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/05/2008	Remediation	2.878	040813895-0006	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060508-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/05/2008	Remediation	2.882	040813895-0007	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060508-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/05/2008	Remediation	2.876	040813895-0008	06/07/2008	06/11/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060608-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/06/2008	Remediation	2.872	040814016-0001	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060608-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/06/2008	Remediation	2.876	040814016-0002	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060608-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/06/2008	Remediation	2.874	040814016-0003	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060608-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/06/2008	Remediation	2.874	040814016-0004	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060608-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/06/2008	Remediation	2.872	040814016-0005	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060608-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/06/2008	Remediation	2.874	040814016-0006	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060608-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/06/2008	Remediation	2.874	040814016-0007	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/12/2008	No	No	See Note 1
EMSL	FH-060608-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/06/2008	Remediation	2.872	040814016-0008	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/12/2008	No	No	
EMSL	FH-060708-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/07/2008	Remediation	2.886	040814024-0001	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060708-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/07/2008	Remediation	2.882	040814024-0002	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060708-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/07/2008	Remediation	2.886	040814024-0003	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060708-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/07/2008	Remediation	2.886	040814024-0004	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060708-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/07/2008	Remediation	2.886	040814024-0005	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060708-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/07/2008	Remediation	2.886	040814024-0006	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060708-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/07/2008	Remediation	2.884	040814024-0007	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060708-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/07/2008	Remediation	2.886	040814024-0008	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060808-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/08/2008	Remediation	2.899	040814022-0001	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060808-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/08/2008	Remediation	2.886	040814022-0002	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	5	06/12/2008	No	No	
EMSL	FH-060808-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/08/2008	Remediation	2.884	040814022-0003	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060808-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/08/2008	Remediation	2.886	040814022-0004	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060808-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/08/2008	Remediation	2.888	040814022-0005	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/12/2008	No	No	
EMSL	FH-060808-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/08/2008	Remediation	2.886	040814022-0006	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/12/2008	No	No	
EMSL	FH-060808-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/08/2008	Remediation	2.888	040814022-0007	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	4	06/12/2008	No	No	
EMSL	FH-060808-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/08/2008	Remediation	2.890	040814022-0008	06/10/2008	06/12/2008	NIOSH 7500 XRD	Silica-Quartz	<3	06/12/2008	No	No	

Note 1: Secondary quartz peak used for sample due to suspected primary peak interference.

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Dioxin/Furans Concentration (ng/m ³)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.00025				
EPA Site Specific Trigger Levels											0.025				
STL-SAC	FH-060708-40	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100302003	06/10/2008	06/27/2008	TO-9	Toxicity Equivalent Quotient (TEQ)	0.0000197	06/30/2008	No	No	

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	PAHs Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.034				
EPA Site Specific Trigger Levels											3.4				
STL-SAC	FH-060708-49	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100301003	06/10/2008	06/18/2008	8270C SIM	BAP-equivalent	<0.007	06/23/2008	No	No	

Submittal Summary - Remediation Phase Week 58 (06/02/08 to 06/08/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	PCBs Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.12				
EPA Site Specific Trigger Levels											12				
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1016	<0.0021	06/20/2008	No	No	
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1221	<0.0021	06/20/2008	No	No	
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1232	<0.0021	06/20/2008	No	No	
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1242	<0.0021	06/20/2008	No	No	
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1248	<0.0021	06/20/2008	No	No	
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1254	<0.0021	06/20/2008	No	No	
STL-SAC	FH-060708-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/7/2008	Remediation	360	G8F100300003	06/10/2008	06/17/2008	TO-4	Aroclor 1260	<0.0021	06/20/2008	No	No	