

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Asbestos PCME Concentration (f/cm ³)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels															
EPA Site Specific Trigger Levels															
0.0009															
N/A															
EMSL	2 FH-060908-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/9/2008	2/Remediation	3.240	030817704-0001	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/9/2008	2/Remediation	3.240	030817704-0002	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/9/2008	2/Remediation	3.240	030817704-0003	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/9/2008	2/Remediation	3.234	030817704-0004	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/9/2008	2/Remediation	3.240	030817704-0005	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/9/2008	2/Remediation	3.234	030817704-0006	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/9/2008	2/Remediation	3.240	030817704-0007	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-060908-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/9/2008	2/Remediation	3.240	030817704-0008	6/10/2008	6/10/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/10/2008	2/Remediation	3.246	030817818-0001	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/10/2008	2/Remediation	3.240	030817818-0002	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/10/2008	2/Remediation	3.252	030817818-0003	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/10/2008	2/Remediation	3.246	030817818-0004	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/10/2008	2/Remediation	3.246	030817818-0005	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/10/2008	2/Remediation	3.240	030817818-0006	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/10/2008	2/Remediation	3.246	030817818-0007	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/10/2008	2/Remediation	3.246	030817818-0008	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061008-65	DUPLICATE (STATION #1)	6/10/2008	2/Remediation	3.246	030817818-0009	6/11/2008	6/12/2008	PCME	ASBESTOS	<0.00083	6/12/2008	No	No	
EMSL	2 FH-061108-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/11/2008	2/Remediation	3.240	030817951-0001	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/11/2008	2/Remediation	3.234	030817951-0002	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/11/2008	2/Remediation	3.240	030817951-0003	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/11/2008	2/Remediation	3.234	030817951-0004	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/11/2008	2/Remediation	3.240	030817951-0005	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/11/2008	2/Remediation	3.234	030817951-0006	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/11/2008	2/Remediation	3.234	030817951-0007	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061108-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/11/2008	2/Remediation	3.240	030817951-0008	6/12/2008	6/13/2008	PCME	ASBESTOS	<0.00076	6/13/2008	No	No	
EMSL	2 FH-061208-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/12/2008	2/Remediation	3.252	030818156-0001	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/12/2008	2/Remediation	3.240	030818156-0002	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/12/2008	2/Remediation	3.234	030818156-0003	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/12/2008	2/Remediation	3.234	030818156-0004	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/12/2008	2/Remediation	3.240	030818156-0005	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/12/2008	2/Remediation	3.234	030818156-0006	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/12/2008	2/Remediation	3.234	030818156-0007	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061208-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/12/2008	2/Remediation	3.246	030818156-0008	6/13/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061308-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/13/2008	2/Remediation	3.240	030818325-0001	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00076	6/16/2008	No	No	
EMSL	2 FH-061308-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/13/2008	2/Remediation	3.228	030818325-0002	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	
EMSL	2 FH-061308-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	2/Remediation	3.234	030818325-0003	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	
EMSL	2 FH-061308-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/13/2008	2/Remediation	3.234	030818325-0004	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	
EMSL	2 FH-061308-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/13/2008	2/Remediation	3.234	030818325-0005	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	
EMSL	2 FH-061308-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/13/2008	2/Remediation	3.228	030818325-0006	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	
EMSL	2 FH-061308-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/13/2008	2/Remediation	3.228	030818325-0007	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	
EMSL	2 FH-061308-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/13/2008	2/Remediation	3.240	030818325-0008	6/14/2008	6/14/2008	PCME	ASBESTOS	<0.00083	6/16/2008	No	No	

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Airetek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Asbestos AHERA Concentration (S/mm ²)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											N/A				
EPA Site Specific Trigger Levels											70				
EMSL	2 FH-060908-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/9/2008	2/Remediation	3.240	030817704-0001	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/9/2008	2/Remediation	3.240	030817704-0002	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/9/2008	2/Remediation	3.240	030817704-0003	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/9/2008	2/Remediation	3.234	030817704-0004	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/9/2008	2/Remediation	3.240	030817704-0005	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/9/2008	2/Remediation	3.234	030817704-0006	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/9/2008	2/Remediation	3.240	030817704-0007	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-060908-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/9/2008	2/Remediation	3.240	030817704-0008	6/10/2008	6/10/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/10/2008	2/Remediation	3.246	030817818-0001	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/10/2008	2/Remediation	3.240	030817818-0002	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/10/2008	2/Remediation	3.252	030817818-0003	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/10/2008	2/Remediation	3.246	030817818-0004	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/10/2008	2/Remediation	3.246	030817818-0005	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/10/2008	2/Remediation	3.240	030817818-0006	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/10/2008	2/Remediation	3.246	030817818-0007	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061008-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER DUPLICATE (STATION #1)	6/10/2008	2/Remediation	3.246	030817818-0008	6/11/2008	6/12/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/12/2008	No	No	
EMSL	2 FH-061108-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/11/2008	2/Remediation	3.240	030817951-0001	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/11/2008	2/Remediation	3.234	030817951-0002	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/11/2008	2/Remediation	3.240	030817951-0003	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/11/2008	2/Remediation	3.234	030817951-0004	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/11/2008	2/Remediation	3.240	030817951-0005	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/11/2008	2/Remediation	3.234	030817951-0006	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/11/2008	2/Remediation	3.234	030817951-0007	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061108-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/11/2008	2/Remediation	3.240	030817951-0008	6/12/2008	6/13/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/13/2008	No	No	
EMSL	2 FH-061208-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/12/2008	2/Remediation	3.252	030818156-0001	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/12/2008	2/Remediation	3.240	030818156-0002	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/12/2008	2/Remediation	3.234	030818156-0003	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/12/2008	2/Remediation	3.234	030818156-0004	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/12/2008	2/Remediation	3.240	030818156-0005	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/12/2008	2/Remediation	3.234	030818156-0006	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/12/2008	2/Remediation	3.234	030818156-0007	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061208-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/12/2008	2/Remediation	3.246	030818156-0008	6/13/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061308-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/13/2008	2/Remediation	3.240	030818325-0001	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/16/2008	No	No	
EMSL	2 FH-061308-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/13/2008	2/Remediation	3.228	030818325-0002	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	
EMSL	2 FH-061308-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	2/Remediation	3.234	030818325-0003	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	
EMSL	2 FH-061308-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/13/2008	2/Remediation	3.234	030818325-0004	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	
EMSL	2 FH-061308-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/13/2008	2/Remediation	3.234	030818325-0005	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	
EMSL	2 FH-061308-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/13/2008	2/Remediation	3.228	030818325-0006	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	
EMSL	2 FH-061308-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/13/2008	2/Remediation	3.228	030818325-0007	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	
EMSL	2 FH-061308-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/13/2008	2/Remediation	3.240	030818325-0008	6/14/2008	6/14/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<15.00	6/16/2008	No	No	

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 2.5 (ug/m ³)	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
							40			
							65			
EPA Site Specific Trigger Levels										
FH-060908-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	20.54	No	No	
FH-060908-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	14.31	No	No	See Note 1
FH-060908-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	24.24	No	No	
FH-060908-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	19.33	No	No	
FH-060908-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	21.81	No	No	
FH-060908-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	22.81	No	No	
FH-060908-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	17.10	No	No	
FH-060908-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	23.63	No	No	
FH-060908-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/9/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	20.79	No	No	
FH-061008-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	34.33	No	No	
FH-061008-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	9.33	No	No	See Note 1
FH-061008-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	16.71	No	No	
FH-061008-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	33.07	No	No	
FH-061008-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	18.15	No	No	
FH-061008-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	37.57	No	No	
FH-061008-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	20.91	No	No	
FH-061008-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	37.19	No	No	
FH-061008-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/10/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	31.42	No	No	
FH-061108-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	8.90	No	No	
FH-061108-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	26.22	No	No	
FH-061108-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.43	No	No	
FH-061108-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.51	No	No	
FH-061108-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	13.93	No	No	
FH-061108-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.58	No	No	
FH-061108-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	8.92	No	No	
FH-061108-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.13	No	No	
FH-061108-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/11/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	8.50	No	No	
FH-061208-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	8.01	No	No	
FH-061208-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.87	No	No	
FH-061208-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	16.85	No	No	
FH-061208-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	9.35	No	No	
FH-061208-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	5.87	No	No	
FH-061208-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	10.44	No	No	
FH-061208-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	8.66	No	No	
FH-061208-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	13.54	No	No	
FH-061208-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/12/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	9.67	No	No	
FH-061308-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.67	No	No	
FH-061308-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	9.53	No	No	
FH-061308-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	22.82	No	No	
FH-061308-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	11.56	No	No	
FH-061308-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	8.08	No	No	
FH-061308-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	12.85	No	No	
FH-061308-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	14.85	No	No	
FH-061308-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	14.50	No	No	
FH-061308-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/13/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	11.67	No	No	
FH-061408-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	39.70	No	No	
FH-061408-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	32.14	No	No	
FH-061408-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	30.42	No	No	
FH-061408-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	39.17	No	No	
FH-061408-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	24.89	No	No	
FH-061408-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	38.60	No	No	
FH-061408-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	20.62	No	No	
FH-061408-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	30.54	No	No	
FH-061408-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/14/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	24.82	No	No	See Note 2
FH-061508-EBAM2.5-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	28.01	No	No	
FH-061508-EBAM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	26.80	No	No	
FH-061508-EBAM2.5-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	28.32	No	No	
FH-061508-EBAM2.5-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	21.55	No	No	
FH-061508-EBAM2.5-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	21.66	No	No	
FH-061508-EBAM2.5-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	22.55	No	No	
FH-061508-EBAM2.5-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	13.58	No	No	
FH-061508-EBAM2.5-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	MetOne EBAM PM 2.5	21.44	No	No	
FH-061508-TEOM2.5-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/15/2008	1440	Particulate 2.5	Direct Real-time Readings	TEOM PM 2.5	17.94	No	No	See Note 2

Note 1: Partial data - Hardware failure due to filter sensor.
 Note 2: Partial data due to tripped electrical panel breaker.

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 10 (ug/m ³)	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
							150			
							150			
							150			
EPA Site Specific Trigger Levels										
FH-060908-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	18.88	No	No	
FH-060908-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	41.27	No	No	
FH-060908-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	13.80	No	No	See Note 1
FH-060908-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	36.43	No	No	
FH-060908-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.66	No	No	
FH-060908-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	38.17	No	No	
FH-060908-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	33.91	No	No	
FH-060908-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.94	No	No	
FH-060908-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/9/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	38.36	No	No	
FH-061008-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	18.89	No	No	
FH-061008-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	58.69	No	No	
FH-061008-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.95	No	No	See Note 1
FH-061008-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	57.01	No	No	
FH-061008-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	55.43	No	No	
FH-061008-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	50.81	No	No	
FH-061008-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	41.28	No	No	
FH-061008-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	44.44	No	No	
FH-061008-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/10/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	64.90	No	No	See Note 2
FH-061108-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	14.16	No	No	
FH-061108-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	39.51	No	No	
FH-061108-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	34.83	No	No	
FH-061108-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.11	No	No	
FH-061108-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.92	No	No	
FH-061108-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.39	No	No	
FH-061108-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.22	No	No	
FH-061108-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.52	No	No	
FH-061108-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/11/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	16.94	No	No	See Note 2
FH-061208-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.90	No	No	
FH-061208-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	17.96	No	No	
FH-061208-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.19	No	No	
FH-061208-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.87	No	No	
FH-061208-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.46	No	No	
FH-061208-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.44	No	No	
FH-061208-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.24	No	No	
FH-061208-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.12	No	No	
FH-061208-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/12/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	23.91	No	No	
FH-061308-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	35.06	No	No	
FH-061308-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.33	No	No	
FH-061308-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.95	No	No	
FH-061308-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.71	No	No	
FH-061308-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.94	No	No	
FH-061308-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.16	No	No	
FH-061308-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	21.72	No	No	
FH-061308-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	29.45	No	No	
FH-061308-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/13/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	40.11	No	No	
FH-061408-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	42.75	No	No	
FH-061408-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	56.52	No	No	
FH-061408-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	44.13	No	No	
FH-061408-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	33.98	No	No	
FH-061408-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	47.07	No	No	
FH-061408-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	73.29	No	No	
FH-061408-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	30.07	No	No	
FH-061408-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.58	No	No	
FH-061408-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/14/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	43.79	No	No	See Note 2
FH-061508-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.53	No	No	
FH-061508-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	31.34	No	No	
FH-061508-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.47	No	No	
FH-061508-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	30.71	No	No	
FH-061508-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.48	No	No	
FH-061508-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	32.33	No	No	
FH-061508-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	34.65	No	No	
FH-061508-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.21	No	No	
FH-061508-TEOM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/15/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	61.58	No	No	See Note 2

Note 1: Partial data - Hardware failure due to filter sensor.
 Note 2: Partial data due to tripped electrical panel breaker.

Submittal Summary - Remediation Phase Week 53 (06/09/08 to 06/15/08)

Ohio Lumex Daily Mercury Readings
all readings are in ng/m³

Target air quality level: 300 ng/m³

USEPA site specific mercury trigger level: 3000 ng/m³

Exceedances: None
Exceedances: None

3 Site Tours Conducted per Work Shift

DATE: 6/9/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	0900-0905	Tour 1	21	20	27	26	26	25	23	19	18	21	20	21	22	23		
	1200-1205	Tour 2	21	22	22	23	22	26	25	26	26	25	26	24	21	21		
	1500-1505	Tour 3	21	21	21	20	19	18	18	21	26	27	26	21	21	21		
5th FLOOR	0910-0915	Tour 1	21	28	27	26	28	28	29	31	28	28	29	21	27	20		
	1210-1215	Tour 2	20	19	21	26	25	26	26	27	26	25	26	21	24	20		
	1510-1515	Tour 3	21	22	21	27	21	26	25	26	27	26	28	26	28	28		
ROOF PERIMETER	0925-0930	Tour 1	21	22	23	23	25	26	26	27	26	27	26	25	24	25		
	1225-1230	Tour 2	21	18	18	19	21	21	24	21	26	25	26	25	22	28		
	1525-1530	Tour 3	18	19	21	21	22	23	26	26	28	29	30	29	24	24		

DATE: 6/9/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	1700-1705	Tour 1	22	25	21	20	27	23	25	21	22	25	26	24	23	22		
	2000-2005	Tour 2	24	26	25	27	23	22	23	25	27	24	25	25	24	25		
	0000-0005	Tour 3	23	21	27	28	25	24	26	21	23	24	21	25	24	20		
5th FLOOR	1710-1715	Tour 1	19	20	21	27	26	28	23	23	25	21	26	26	23	23		
	2010-2015	Tour 2	23	26	25	23	21	25	24	27	26	20	22	19	23	22		
	0010-0015	Tour 3	22	20	25	26	19	23	27	25	26	27	21	23	23	23		
ROOF PERIMETER	1725-1730	Tour 1	25	24	25	20	26	27	25	24	28	21	23	22	23	23		
	2025-2030	Tour 2	24	21	24	23	27	29	21	23	23	24	25	23	23	22		
	0025-0030	Tour 3	23	28	28	24	25	21	27	25	21	22	24	24	24	24		

DATE: 6/10/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	0900-0905	Tour 1	17	22	20	19	23	23	18	21	24	21	24	17	20	17		
	1200-1205	Tour 2	19	21	24	17	18	22	20	23	19	24	17	18	20	19		
	1500-1505	Tour 3	20	19	18	23	17	19	24	20	22	21	23	17	20	17		
5th FLOOR	0910-0915	Tour 1	23	20	18	24	22	17	24	23	18	21	19	21	20	19		
	1210-1215	Tour 2	19	17	23	20	18	24	23	17	20	20	19	23	20	19		
	1510-1515	Tour 3	18	19	23	21	24	17	23	20	19	18	20	17	19	17		
ROOF PERIMETER	0925-0930	Tour 1	19	20	24	22	17	18	17	23	19	24	20	21	20	19		
	1225-1230	Tour 2	17	17	18	19	20	17	24	22	17	24	18	20	19	18		
	1525-1530	Tour 3	20	17	18	23	24	22	20	21	19	18	17	24	20	19		

DATE: 6/10/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	1700-1705	Tour 1	24	26	25	21	18	19	18	19	23	27	21	24	22	20		
	2000-2005	Tour 2	23	22	23	28	24	21	25	18	19	21	23	20	20	19		
	0000-0005	Tour 3	21	19	17	23	26	21	24	21	23	25	21	22	21	20		
5th FLOOR	1710-1715	Tour 1	21	23	19	24	23	19	20	17	19	23	20	21	20	19		
	2010-2015	Tour 2	23	23	23	20	19	18	22	21	23	22	20	21	21	20		
	0010-0015	Tour 3	21	19	16	18	17	21	21	19	17	18	17	20	19	18		
ROOF PERIMETER	1725-1730	Tour 1	22	20	21	16	19	20	18	17	22	21	19	20	19	18		
	2025-2030	Tour 2	19	20	17	24	21	26	17	21	20	23	20	22	20	19		
	0025-0030	Tour 3	20	19	17	20	17	18	20	21	21	19	19	17	19	18		

DATE: 6/11/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	0900-0905	Tour 1	20	18	18	23	17	21	18	23	24	20	17	19	19	18		
	1200-1205	Tour 2	17	24	22	18	17	22	19	23	17	22	24	21	20	19		
	1500-1505	Tour 3	20	19	18	24	17	19	20	21	24	22	17	20	20	19		
5th FLOOR	0910-0915	Tour 1	19	17	23	22	17	21	18	24	19	17	23	22	20	19		
	1210-1215	Tour 2	18	20	17	24	22	20	17	23	19	24	19	17	20	19		
	1510-1515	Tour 3	17	24	20	17	24	19	18	22	20	17	19	24	20	19		
ROOF PERIMETER	0925-0930	Tour 1	22	20	17	24	19	21	19	24	20	17	18	19	20	19		
	1225-1230	Tour 2	19	24	18	20	17	23	20	24	19	23	24	21	20	19		
	1525-1530	Tour 3	20	17	23	17	18	22	20	19	23	17	19	21	20	19		

DATE: 6/11/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	1700-1705	Tour 1	23	19	20	18	22	25	24	22	24	19	21	23	21	20		
	2000-2005	Tour 2	23	20	21	17	20	22	19	24	21	20	23	19	20	19		
	0000-0005	Tour 3	21	19	19	26	22	23	18	17	20	21	19	20	20	19		
5th FLOOR	1710-1715	Tour 1	19	22	20	22	17	19	20	24	22	23	20	19	20	19		
	2010-2015	Tour 2	24	19	20	23	21	27	25	23	26	19	17	18	21	20		
	0010-0015	Tour 3	20	22	24	19	18	20	23	21	22	20	23	21	21	20		
ROOF PERIMETER	1725-1730	Tour 1	21	24	23	20	22	25	18	20	17	16	19	20	20	19		
	2025-2030	Tour 2	22	20	23	24	21	19	20	17	21	22	18	23	20	19		
	0025-0030	Tour 3	17	23	21	25	24	26	24	22	25	23	20	21	20	19		

DATE: 6/12/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	0900-0905	Tour 1	19	20	23	17	24	19	22	17	18	20	24	23	20	19		
	1200-1205	Tour 2	17	22	19	24	17	17	20	23	19	24	20	22	20	19		
	1500-1505	Tour 3	19	23	17	18	24	20	23	22	24	17	24	19	20	19		
5th FLOOR	0910-0915	Tour 1	19	18	24	22	17	23	19	24	20	22	21	20	20	19		
	1210-1215	Tour 2	17	24	20	19	23	17	18	20	24	19	23	22	20	19		
	1510-1515	Tour 3	21	17	24	18	20	19	23	24	17	20	19	23	20	19		
ROOF PERIMETER	0925-0930	Tour 1	24	17	20	21	18	23	23	20	17	18	23	24	20	19		
	1225-1230	Tour 2	20	17	19	23	24	20	17	21	19	24	22	20	20	19		
	1525-1530	Tour 3	18	20	24	17	19	17	22	18	20	17	23	22	20	19		

DATE: 6/12/2008 2nd SHIFT

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	1700-1705	Tour 1	22	19	21	25	23	20	21	19	16	21	20	22	20	19		
	2000-2005	Tour 2	21	22	24	20	19	18	23	19	21	23	20	24	21	20		
	0000-0005	Tour 3	19	20	17	22	20	21	17	22	20	21	18	20	19	18		
5th FLOOR	1710-1715	Tour 1	20	18	23	21	22	26	22	23	20	19	17	20	20	19		
	2010-2015	Tour 2	17	17	19	18	23	24	22	28	26	21	22	21	20	19		
	0010-0015	Tour 3	23	21	25	23	23	19	18	20	21	22	19	20	20	19		
ROOF PERIMETER	1725-1730	Tour 1	22	20	23	19	24	21	22	18	16	19	20	19	20	19		
	2025-2030	Tour 2	24	23	25	28	23	24	20	22	19	20	18	18	22	20		
	0025-0030	Tour 3	20	20	20	18	20	19	18	21	17	22	21	18	19	18		

DATE: 6/13/2008

AREA:	TIME:	Tour #:	TOUR AVERAGE:															
PERIMETER OF BUILDING	0900-0905	Tour 1	19	22	20	17	17	23	18	19	24	20	17	22	20	19		
	1200-1205	Tour 2	24	17	19	22	17	20	17	19	23	20	24	18	20	19		
	1500-1505	Tour 3	19	24	20	17	23	18	14	20	19	18	23	22	20	19		
5th FLOOR	0910-0915	Tour 1	20	23	17	23	19	24	21	19	18	20	23	17	20	19		
	1210-1215	Tour 2	23	17	19	24	18	20	24	23	20	17	20	19	20	19		
	1510-1515	Tour 3	18	24	20	17	19	24	22	17	19	23	24	24	20	19		
ROOF PERIMETER	0925-0930	Tour 1	22	19	20	17	18	24	20	17	18	22	24	17	20	19		
	1225-1230	Tour 2	1															

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Field Sample ID	Sample Location	Date Collected	Project Phase	Sample Volume (m3)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Antimony Concentration (ug/m ³)	Barium Concentration (ug/m ³)	Beryllium Concentration (ug/m ³)	Cadmium Concentration (ug/m ³)	Chromium (Total) Concentration (ug/m ³)	Copper Concentration (ug/m ³)	Lead Concentration (ug/m ³)	Manganese Concentration (ug/m ³)	Nickel Concentration (ug/m ³)	Zinc Concentration (ug/m ³)	Unit	Flag	Qualifier	Date Reported	Exceeds Target Air Quality Level?	Exceeds EPA Site Specific Trigger Level?	Comments						
Target Air Quality Levels										5,000	5,000	20	50	2,000	500	1,000	500	200	16,000													
EPA Site Specific Trigger Levels										14,000	14,000	200	500	100,000	10	200	100	200	16,000													
STL-SAC	PH-060908-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/9/2008	Remediation	5.752	GSF 101185001	6/11/2008	6/13/2008	6020	-34.8	-174	-17.4	-17.4	-174	-86.9	-17.4	-86.9	-86.9	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/9/2008	Remediation	5.764	GSF 101185002	6/11/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/9/2008	Remediation	5.764	GSF 101185003	6/11/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/9/2008	Remediation	5.76	GSF 101185004	6/11/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/9/2008	Remediation	5.76	GSF 101185005	6/11/2008	6/13/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/9/2008	Remediation	5.76	GSF 101185006	6/11/2008	6/13/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/9/2008	Remediation	5.764	GSF 101185007	6/11/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-060908-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/9/2008	Remediation	5.76	GSF 101185008	6/11/2008	6/13/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/16/2008	No	No							
STL-SAC	PH-061008-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/10/2008	Remediation	5.768	GSF 120189001	6/12/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/10/2008	Remediation	5.768	GSF 120189002	6/12/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/10/2008	Remediation	5.768	GSF 120189003	6/12/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/10/2008	Remediation	5.772	GSF 120189004	6/12/2008	6/13/2008	6020	-34.6	-173	-17.3	-17.3	-173	-86.6	-17.3	-86.6	-86.6	-346	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/10/2008	Remediation	5.772	GSF 120189005	6/12/2008	6/13/2008	6020	-34.6	-173	-17.3	-17.3	-173	-86.6	-17.3	-86.6	-86.6	-346	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/10/2008	Remediation	5.772	GSF 120189006	6/12/2008	6/13/2008	6020	-34.6	-173	-17.3	-17.3	-173	-86.6	-17.3	-86.6	-86.6	-346	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/10/2008	Remediation	5.768	GSF 120189007	6/12/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/10/2008	Remediation	5.772	GSF 120189008	6/12/2008	6/13/2008	6020	-34.6	-173	-17.3	-17.3	-173	-86.6	-17.3	-86.6	-86.6	-346	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061008-67	DUPLICATE (STATION #1)	6/10/2008	Remediation	5.768	GSF 120189010	6/12/2008	6/13/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/17/2008	No	No							
STL-SAC	PH-061108-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/11/2008	Remediation	5.772	GSF 130151001	6/13/2008	6/17/2008	6020	-34.6	-173	-17.3	-17.3	-173	-86.6	-17.3	-86.6	-86.6	-346	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/11/2008	Remediation	5.76	GSF 130151002	6/13/2008	6/17/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/11/2008	Remediation	5.76	GSF 130151003	6/13/2008	6/17/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/11/2008	Remediation	5.76	GSF 130151004	6/13/2008	6/17/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/11/2008	Remediation	5.76	GSF 130151005	6/13/2008	6/17/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/11/2008	Remediation	5.76	GSF 130151006	6/13/2008	6/18/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/11/2008	Remediation	5.76	GSF 130151007	6/13/2008	6/18/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.8	-17.4	-86.8	-86.8	-347	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061108-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/11/2008	Remediation	5.772	GSF 130151008	6/13/2008	6/18/2008	6020	-34.6	-173	-17.3	-17.3	-173	-86.6	-17.3	-86.6	-86.6	-346	ng/m ³			6/18/2008	No	No							
STL-SAC	PH-061208-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/12/2008	Remediation	5.764	GSF 160152001	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/12/2008	Remediation	5.768	GSF 160152002	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/12/2008	Remediation	5.768	GSF 160152003	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/12/2008	Remediation	5.768	GSF 160152004	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/12/2008	Remediation	5.768	GSF 160152005	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-25	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/12/2008	Remediation	5.768	GSF 160152006	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-26	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/12/2008	Remediation	5.768	GSF 160152007	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061208-27	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/12/2008	Remediation	5.764	GSF 160152008	6/16/2008	6/18/2008	6020	-34.7	-173	-17.3	-17.3	-173	-86.7	-17.3	-86.7	-86.7	-347	ng/m ³			6/19/2008	No	No							
STL-SAC	PH-061308-20	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/13/2008	Remediation	5.76	GSF 170240001	6/17/2008	6/19/2008	6020	-34.8	-174	-17.4	-17.4	-174	-86.9	-17.4	-86.8	-86.8	-347	ng/m ³			6/20/2008	No	No							
STL-SAC	PH-061308-21	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/13/2008	Remediation	5.744	GSF 170240002	6/17/2008	6/19/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.9	-17.4	-87.0	-86.9	-348	ng/m ³			6/20/2008	No	No							
STL-SAC	PH-061308-22	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	5.752	GSF 170240003	6/17/2008	6/19/2008	6020	-34.8	-174	-17.4	-17.4	-174	-86.9	-17.4	-86.9	-86.9	-348	ng/m ³			6/20/2008	No	No							
STL-SAC	PH-061308-23	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/13/2008	Remediation	5.752	GSF 170240004	6/17/2008	6/19/2008	6020	-34.8	-174	-17.4	-17.4	-174	-86.9	-17.4	-86.9	-86.9	-348	ng/m ³			6/20/2008	No	No							
STL-SAC	PH-061308-24	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/13/2008	Remediation	5.756	GSF 170240005	6/17/2008	6/19/2008	6020	-34.7	-174	-17.4	-17.4	-174	-86.9	-17.4	-86.9	-86.9	-347	ng/m ³			6/20/2008	No	No							
STL-SAC	PH-061308-25	#6 - 5TH FLOOR SETBACK ROOF SW SW SIDE	6/13/2008	Remediation	5.752	GSF 170240006	6/17/2008	6/19/2008	6020	-34.8	-174	-17.4	-17.4	-174	-86.9	-17.4	-86.9	-86.9														

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Silica-Quartz Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels												10			
EPA Site Specific Trigger Levels												10			
EMSL	FH-060908-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/09/2008	Remediation	2.876	040814164-0001	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/13/2008	No	No	
EMSL	FH-060908-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/09/2008	Remediation	2.882	040814164-0002	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/13/2008	No	No	
EMSL	FH-060908-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/09/2008	Remediation	2.882	040814164-0003	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/13/2008	No	No	
EMSL	FH-060908-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/09/2008	Remediation	2.880	040814164-0004	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-060908-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/09/2008	Remediation	2.880	040814164-0005	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-060908-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/09/2008	Remediation	2.880	040814164-0006	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-060908-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/09/2008	Remediation	2.882	040814164-0007	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/13/2008	No	No	
EMSL	FH-060908-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/09/2008	Remediation	2.880	040814164-0008	06/11/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<3	06/13/2008	No	No	
EMSL	FH-061008-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/10/2008	Remediation	2.884	040814280-0001	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/13/2008	No	No	
EMSL	FH-061008-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/10/2008	Remediation	2.884	040814280-0002	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/13/2008	No	No	
EMSL	FH-061008-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/10/2008	Remediation	2.884	040814280-0003	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-061008-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/10/2008	Remediation	2.886	040814280-0004	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	9	06/13/2008	No	No	
EMSL	FH-061008-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/10/2008	Remediation	2.886	040814280-0005	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-061008-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/10/2008	Remediation	2.886	040814280-0006	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-061008-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/10/2008	Remediation	2.884	040814280-0007	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-061008-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/10/2008	Remediation	2.886	040814280-0008	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-061008-68	DUPLICATE (STATION #1)	06/10/2008	Remediation	2.884	040814280-0010	06/12/2008	06/13/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/13/2008	No	No	
EMSL	FH-061108-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/11/2008	Remediation	2.886	040814375-0001	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/16/2008	No	No	
EMSL	FH-061108-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/11/2008	Remediation	2.880	040814375-0002	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	5	06/16/2008	No	No	
EMSL	FH-061108-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/11/2008	Remediation	2.880	040814375-0003	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/16/2008	No	No	
EMSL	FH-061108-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/11/2008	Remediation	2.880	040814375-0004	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/16/2008	No	No	
EMSL	FH-061108-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/11/2008	Remediation	2.880	040814375-0005	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/16/2008	No	No	
EMSL	FH-061108-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/11/2008	Remediation	2.880	040814375-0006	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/16/2008	No	No	
EMSL	FH-061108-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/11/2008	Remediation	2.880	040814375-0007	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/16/2008	No	No	
EMSL	FH-061108-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/11/2008	Remediation	2.886	040814375-0008	06/13/2008	06/14/2008	NIOSH 7500 XRD	Silica-Quartz	7	06/16/2008	No	No	
EMSL	FH-061208-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/12/2008	Remediation	2.882	040814506-0001	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	5	06/17/2008	No	No	
EMSL	FH-061208-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/12/2008	Remediation	2.884	040814506-0002	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	8	06/17/2008	No	No	
EMSL	FH-061208-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/12/2008	Remediation	2.884	040814506-0003	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	4	06/17/2008	No	No	
EMSL	FH-061208-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/12/2008	Remediation	2.884	040814506-0004	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/17/2008	No	No	
EMSL	FH-061208-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/12/2008	Remediation	2.884	040814506-0005	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/17/2008	No	No	
EMSL	FH-061208-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/12/2008	Remediation	2.884	040814506-0006	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/17/2008	No	No	
EMSL	FH-061208-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/12/2008	Remediation	2.884	040814506-0007	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/17/2008	No	No	
EMSL	FH-061208-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/12/2008	Remediation	2.882	040814506-0008	06/14/2008	06/17/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/17/2008	No	No	
EMSL	FH-061308-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/13/2008	Remediation	2.880	040814575-0001	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061308-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/13/2008	Remediation	2.872	040814575-0002	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	10.4	06/20/2008	Yes	Yes	See Note 1
EMSL	FH-061308-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/13/2008	Remediation	2.878	040814575-0003	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	8	06/20/2008	No	No	
EMSL	FH-061308-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/13/2008	Remediation	2.878	040814575-0004	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061308-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/13/2008	Remediation	2.878	040814575-0005	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061308-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/13/2008	Remediation	2.876	040814575-0006	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061308-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/13/2008	Remediation	2.872	040814575-0007	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061308-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/13/2008	Remediation	2.880	040814575-0008	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/14/2008	Remediation	2.876	040814658-0001	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/14/2008	Remediation	2.884	040814658-0002	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/14/2008	Remediation	2.880	040814658-0003	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/14/2008	Remediation	2.878	040814658-0004	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/14/2008	Remediation	2.876	040814658-0005	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/14/2008	Remediation	2.878	040814658-0006	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061408-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/14/2008	Remediation	2.884	040814658-0007	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061408-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/14/2008	Remediation	2.876	040814658-0008	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/20/2008	No	No	
EMSL	FH-061508-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/15/2008	Remediation	2.876	040814659-0001	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061508-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/15/2008	Remediation	2.876	040814659-0002	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/20/2008	No	No	
EMSL	FH-061508-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/15/2008	Remediation	2.876	040814659-0003	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061508-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/15/2008	Remediation	2.878	040814659-0004	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/20/2008	No	No	
EMSL	FH-061508-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/15/2008	Remediation	2.878	040814659-0005	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061508-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/15/2008	Remediation	2.878	040814659-0006	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061508-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/15/2008	Remediation	2.876	040814659-0007	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	
EMSL	FH-061508-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/15/2008	Remediation	2.876	040814659-0008	06/16/2008	06/20/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/20/2008	No	No	

Note 1: Exceedance of the USEPA Site Specific Trigger Level for silica at Station #2 (Sidewalk Bridge Level SW Corner) occurred on Friday, June 13, 2008. Fugitive emissions likely attribute to one or more off site properties directly impacted silica concentrations. After review of all of the information including meteorological data, PM 10 data, site activities logs and off site visual observations, it has been determined that the silica exceedance measured at Station #2 on June 13, 2008 was not attributable to work activities at 30 West Broadway. Exceedance reported to USEPA.

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Dioxin/Furans Concentration (ng/m ³)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.00025				
EPA Site Specific Trigger Levels											0.025				
STL-SAC	FH-061308-40	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170279003	06/17/2008	06/29/2008	TO-9	Toxicity Equivalent Quotient (TEQ)	0.000024	07/14/2008	No	No	

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	PAHs Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.034				
EPA Site Specific Trigger Levels											3.4				
STL-SAC	FH-061308-49	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170280003	06/17/2008	06/20/2008	8270C SIM	BAP-equivalent	<0.007	06/30/2008	No	No	

Submittal Summary - Remediation Phase Week 59 (06/09/08 to 06/15/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m ³)	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	PCBs Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.12				
EPA Site Specific Trigger Levels											12				
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1016	<0.0021	06/27/2008	No	No	
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1221	<0.0021	06/27/2008	No	No	
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1232	<0.0021	06/27/2008	No	No	
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1242	<0.0021	06/27/2008	No	No	
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1248	<0.0021	06/27/2008	No	No	
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1254	<0.0021	06/27/2008	No	No	
STL-SAC	FH-061308-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/13/2008	Remediation	360	G8F170278003	06/17/2008	06/21/2008	TO-4	Aroclor 1260	<0.0021	06/27/2008	No	No	