



**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m <sup>3</sup> )	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Asbestos PCME Concentration (f/cm <sup>3</sup> )	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels															
EPA Site Specific Trigger Levels															
0.0009															
N/A															
EMSL	2 FH-061608-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/16/2008	2/Remediation	3.252	030818666-0001	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/16/2008	2/Remediation	3.240	030818666-0002	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/16/2008	2/Remediation	3.240	030818666-0003	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/16/2008	2/Remediation	3.240	030818666-0004	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/16/2008	2/Remediation	3.246	030818666-0005	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/16/2008	2/Remediation	3.240	030818666-0006	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/16/2008	2/Remediation	3.240	030818666-0007	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061608-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/16/2008	2/Remediation	3.252	030818666-0008	6/17/2008	6/18/2008	PCME	ASBESTOS	<0.00076	6/18/2008	No	No	
EMSL	2 FH-061708-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/17/2008	2/Remediation	3.240	030818848-0001	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/17/2008	2/Remediation	3.240	030818848-0002	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/17/2008	2/Remediation	3.240	030818848-0003	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/17/2008	2/Remediation	3.234	030818848-0004	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/17/2008	2/Remediation	3.240	030818848-0005	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/17/2008	2/Remediation	3.234	030818848-0006	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/17/2008	2/Remediation	3.240	030818848-0007	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/17/2008	2/Remediation	3.246	030818848-0008	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061708-65	DUPLICATE (STATION # 1)	6/17/2008	2/Remediation	3.240	030818848-0009	6/18/2008	6/19/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/18/2008	2/Remediation	3.252	030819044-0001	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/18/2008	2/Remediation	3.240	030819044-0002	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/18/2008	2/Remediation	3.246	030819044-0003	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/18/2008	2/Remediation	3.246	030819044-0004	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/18/2008	2/Remediation	3.252	030819044-0005	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/18/2008	2/Remediation	3.246	030819044-0006	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/18/2008	2/Remediation	3.240	030819044-0007	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061808-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/18/2008	2/Remediation	3.252	030819044-0008	6/19/2008	6/20/2008	PCME	ASBESTOS	<0.00076	6/20/2008	No	No	
EMSL	2 FH-061908-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/19/2008	2/Remediation	3.240	030819192-0001	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/19/2008	2/Remediation	3.240	030819192-0002	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	2/Remediation	3.240	030819192-0003	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/19/2008	2/Remediation	3.240	030819192-0004	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/19/2008	2/Remediation	3.240	030819192-0005	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/19/2008	2/Remediation	3.240	030819192-0006	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/19/2008	2/Remediation	3.240	030819192-0007	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-061908-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/19/2008	2/Remediation	3.240	030819192-0008	6/20/2008	6/21/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/20/2008	2/Remediation	3.252	030819382-0001	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/20/2008	2/Remediation	3.240	030819382-0002	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/20/2008	2/Remediation	3.246	030819382-0003	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/20/2008	2/Remediation	3.246	030819382-0004	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/20/2008	2/Remediation	3.246	030819382-0005	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/20/2008	2/Remediation	3.246	030819382-0006	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/20/2008	2/Remediation	3.240	030819382-0007	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	
EMSL	2 FH-062008-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/20/2008	2/Remediation	3.252	030819382-0008	6/21/2008	6/22/2008	PCME	ASBESTOS	<0.00076	6/23/2008	No	No	



**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m <sup>3</sup> )	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Asbestos AHERA Concentration (S/mm <sup>3</sup> )	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											N/A				
EPA Site Specific Trigger Levels											70				
EMSL	2 FH-061608-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/16/2008	2/Remediation	3.252	030818666-0001	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/16/2008	2/Remediation	3.240	030818666-0002	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/16/2008	2/Remediation	3.240	030818666-0003	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/16/2008	2/Remediation	3.240	030818666-0004	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/16/2008	2/Remediation	3.246	030818666-0005	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/16/2008	2/Remediation	3.240	030818666-0006	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/16/2008	2/Remediation	3.240	030818666-0007	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061608-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/16/2008	2/Remediation	3.252	030818666-0008	6/17/2008	6/18/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/18/2008	No	No	
EMSL	2 FH-061708-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/17/2008	2/Remediation	3.240	030818848-0001	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/17/2008	2/Remediation	3.240	030818848-0002	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/17/2008	2/Remediation	3.240	030818848-0003	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/17/2008	2/Remediation	3.234	030818848-0004	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/17/2008	2/Remediation	3.240	030818848-0005	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/17/2008	2/Remediation	3.234	030818848-0006	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/17/2008	2/Remediation	3.240	030818848-0007	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/17/2008	2/Remediation	3.246	030818848-0008	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061708-65	DUPLICATE (STATION # 1)	6/17/2008	2/Remediation	3.240	030818848-0009	6/18/2008	6/19/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/18/2008	2/Remediation	3.252	030819044-0001	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/18/2008	2/Remediation	3.240	030819044-0002	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/18/2008	2/Remediation	3.246	030819044-0003	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/18/2008	2/Remediation	3.246	030819044-0004	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/18/2008	2/Remediation	3.252	030819044-0005	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/18/2008	2/Remediation	3.246	030819044-0006	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/18/2008	2/Remediation	3.240	030819044-0007	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061808-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/18/2008	2/Remediation	3.252	030819044-0008	6/19/2008	6/20/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/20/2008	No	No	
EMSL	2 FH-061908-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/19/2008	2/Remediation	3.240	030819192-0001	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/19/2008	2/Remediation	3.240	030819192-0002	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	2/Remediation	3.240	030819192-0003	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/19/2008	2/Remediation	3.240	030819192-0004	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/19/2008	2/Remediation	3.240	030819192-0005	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/19/2008	2/Remediation	3.240	030819192-0006	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/19/2008	2/Remediation	3.240	030819192-0007	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-061908-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/19/2008	2/Remediation	3.240	030819192-0008	6/20/2008	6/21/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/20/2008	2/Remediation	3.252	030819382-0001	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/20/2008	2/Remediation	3.240	030819382-0002	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/20/2008	2/Remediation	3.246	030819382-0003	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/20/2008	2/Remediation	3.246	030819382-0004	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/20/2008	2/Remediation	3.246	030819382-0005	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/20/2008	2/Remediation	3.246	030819382-0006	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/20/2008	2/Remediation	3.240	030819382-0007	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	
EMSL	2 FH-062008-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/20/2008	2/Remediation	3.252	030819382-0008	6/21/2008	6/22/2008	TEM EPA 40 CFR PART 763 (AHERA)	ASBESTOS	<13.00	6/23/2008	No	No	



**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Airtek Field Sample No.	Sampling Location	Real-time Readings Date	Collection time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM 10 (ug/m <sup>3</sup> )	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
							150			
							150			
							150			
FH-061608-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	50.71	No	No	
FH-061608-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.18	No	No	
FH-061608-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.35	No	No	
FH-061608-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	36.78	No	No	
FH-061608-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	43.76	No	No	
FH-061608-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	33.79	No	No	
FH-061608-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	42.90	No	No	
FH-061608-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.06	No	No	
FH-061608-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/16/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	32.35	No	No	See Note 1
FH-061708-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.01	No	No	
FH-061708-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	14.67	No	No	
FH-061708-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	15.72	No	No	
FH-061708-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.64	No	No	
FH-061708-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	21.92	No	No	
FH-061708-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.74	No	No	
FH-061708-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	18.31	No	No	
FH-061708-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	10.60	No	No	
FH-061708-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/17/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	24.99	No	No	
FH-061808-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	20.32	No	No	
FH-061808-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	20.78	No	No	
FH-061808-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	19.33	No	No	
FH-061808-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	27.24	No	No	
FH-061808-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.51	No	No	
FH-061808-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	22.95	No	No	
FH-061808-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	14.22	No	No	
FH-061808-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.01	No	No	
FH-061808-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/18/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	28.92	No	No	
FH-061908-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	38.98	No	No	
FH-061908-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	13.54	No	No	
FH-061908-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	32.06	No	No	
FH-061908-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	23.31	No	No	
FH-061908-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	16.42	No	No	
FH-061908-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	15.34	No	No	
FH-061908-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	16.61	No	No	
FH-061908-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	9.16	No	No	
FH-061908-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/19/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	21.27	No	No	
FH-062008-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	43.88	No	No	
FH-062008-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	21.22	No	No	
FH-062008-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	23.42	No	No	
FH-062008-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	29.32	No	No	
FH-062008-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.90	No	No	
FH-062008-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.74	No	No	
FH-062008-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	17.01	No	No	
FH-062008-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	17.49	No	No	
FH-062008-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/20/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	36.55	No	No	
FH-062108-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.18	No	No	
FH-062108-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	25.46	No	No	
FH-062108-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	30.22	No	No	
FH-062108-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	32.03	No	No	
FH-062108-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	29.55	No	No	
FH-062108-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	32.26	No	No	
FH-062108-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	28.94	No	No	
FH-062108-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	24.27	No	No	
FH-062108-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/21/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	30.79	No	No	See Note 1
FH-062208-EBAM10-01	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	26.67	No	No	
FH-062208-EBAM10-02	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	37.43	No	No	
FH-062208-EBAM10-03	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	30.80	No	No	
FH-062208-EBAM10-04	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	34.04	No	No	
FH-062208-EBAM10-05	#5 - 5TH FLOOR SETBACK ROOF N SIDE	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	38.33	No	No	
FH-062208-EBAM10-06	#6 - 5TH FLOOR SETBACK ROOF SW SIDE	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	46.25	No	No	
FH-062208-EBAM10-07	#7 - 5TH FLOOR SCAFFOLD AT SE CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	32.76	No	No	
FH-062208-EBAM10-08	#8 - 5TH FLOOR SCAFFOLD AT NE CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	MetOne EBAM PM 10	30.09	No	No	
FH-062208-TEOM10-02	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	6/22/2008	1440	Particulate 10	Direct Real-time Readings	TEOM PM 10	33.31	No	No	See Note 1

Note 1: Partial data due to tripped electrical panel breaker.



**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Ohio Lumex Daily Mercury Readings  
all readings are in ng/m<sup>3</sup>

Target air quality level: 300 ng/m<sup>3</sup>

USEPA site specific mercury trigger level: 3000 ng/m<sup>3</sup>

Exceedances: None

Exceedances: None

3 Site Tours Conducted per Work Shift

**DATE: 6/16/2008**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	19	24	20	17	23	18	17	21	19	24	20	22	20.33
	1200-1205	Tour 2	20	17	23	18	19	20	24	22	17	19	23	20	20.17
	1500-1505	Tour 3	17	21	19	24	20	18	17	24	22	19	21	17	19.92
5th FLOOR	0910-0915	Tour 1	19	24	22	17	20	18	21	17	23	20	19	24	20.33
	1210-1215	Tour 2	17	20	23	17	21	17	19	24	22	18	19	23	20.00
	1510-1515	Tour 3	22	19	20	17	24	19	23	17	19	22	20	18	20.00
ROOF PERIMETER	0925-0930	Tour 1	18	24	20	17	23	19	20	22	17	24	23	17	20.33
	1225-1230	Tour 2	20	22	19	24	17	21	19	24	18	22	20	19	20.42
	1525-1530	Tour 3	19	24	17	22	18	24	19	20	28	17	18	24	20.83

**DATE: 6/16/2008 2nd SHIFT**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	26	24	25	21	24	23	19	20	25	24	23	25	23.25
	2000-2005	Tour 2	24	24	23	27	22	24	22	23	20	21	24	23	23.08
	0000-0005	Tour 3	25	23	27	26	21	23	20	18	22	19	23	21	22.33
5th FLOOR	1710-1715	Tour 1	24	25	27	23	22	20	23	22	25	24	21	23	23.25
	2010-2015	Tour 2	21	19	20	18	22	23	21	24	25	21	19	22	21.25
	0010-0015	Tour 3	23	19	24	23	21	20	22	23	19	20	22	21	21.42
ROOF PERIMETER	1725-1730	Tour 1	25	26	25	22	24	21	25	23	23	21	22	24	23.42
	2025-2030	Tour 2	23	21	20	22	20	25	24	26	21	20	23	21	22.17
	0025-0030	Tour 3	19	17	20	22	21	24	21	24	26	23	24	20	21.75

**DATE: 6/17/2008**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	17	20	24	19	18	21	23	24	22	17	19	20	20.33
	1200-1205	Tour 2	19	22	23	17	17	20	22	17	19	22	17	24	19.82
	1500-1505	Tour 3	22	17	20	19	24	17	23	21	18	19	24	20	20.33
5th FLOOR	0910-0915	Tour 1	20	17	19	24	21	20	18	24	20	17	23	18	20.08
	1210-1215	Tour 2	19	24	20	17	21	18	24	17	23	17	19	24	20.25
	1510-1515	Tour 3	17	20	22	22	19	23	17	24	20	18	18	22	20.17
ROOF PERIMETER	0925-0930	Tour 1	17	23	19	20	24	18	22	19	21	17	19	23	20.17
	1225-1230	Tour 2	22	20	19	20	20	23	20	22	19	21	17	17	21.00
	1525-1530	Tour 3	19	24	23	17	19	24	17	21	24	21	17	22	20.87

**DATE: 6/17/2008 2nd SHIFT**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	26	25	26	23	24	18	20	21	19	24	23	24	22.75
	2000-2005	Tour 2	25	25	24	26	23	22	24	25	23	26	23	24	24.17
	0000-0005	Tour 3	21	23	18	22	18	17	23	22	21	23	20	20	20.75
5th FLOOR	1710-1715	Tour 1	23	25	21	22	20	23	26	25	24	23	20	24	23.00
	2010-2015	Tour 2	20	24	25	23	24	20	21	27	25	21	22	19	22.58
	0010-0015	Tour 3	19	20	18	22	21	20	17	16	19	22	23	21	19.83
ROOF PERIMETER	1725-1730	Tour 1	24	23	26	27	24	25	21	22	20	22	26	25	23.75
	2025-2030	Tour 2	23	22	21	24	27	26	23	24	21	20	18	20	22.42
	0025-0030	Tour 3	21	22	20	17	16	18	20	18	22	19	18	19	19.17

**DATE: 6/18/2008**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	17	18	24	23	17	20	18	24	22	23	17	20	20.33
	1200-1205	Tour 2	19	23	22	24	20	17	20	19	24	17	20	18	20.25
	1500-1505	Tour 3	24	22	20	23	17	19	24	17	23	20	17	23	20.75
5th FLOOR	0910-0915	Tour 1	23	17	19	24	20	18	22	24	20	17	19	18	20.08
	1210-1215	Tour 2	24	19	22	20	18	24	21	17	19	20	22	17	20.25
	1510-1515	Tour 3	19	22	20	18	21	17	19	24	22	19	23	22	20.50
ROOF PERIMETER	0925-0930	Tour 1	17	20	24	17	23	19	24	18	23	20	17	19	20.08
	1225-1230	Tour 2	24	22	17	18	19	23	20	24	25	22	23	17	21.00
	1525-1530	Tour 3	19	18	20	24	17	19	23	20	21	23	17	24	20.42

**DATE: 6/18/2008 2nd SHIFT**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	20	19	23	24	22	23	20	21	24	18	23	22	21.58
	2000-2005	Tour 2	19	23	21	22	24	23	25	25	21	19	20	21	21.92
	0000-0005	Tour 3	20	19	22	21	23	19	19	20	17	21	20	21	20.08
5th FLOOR	1710-1715	Tour 1	22	24	24	23	25	21	19	20	18	22	21	23	21.83
	2010-2015	Tour 2	17	18	22	19	21	23	22	23	21	20	22	20	20.67
	0010-0015	Tour 3	18	21	18	21	20	21	23	20	21	23	20	21	20.67
ROOF PERIMETER	1725-1730	Tour 1	20	22	24	21	20	18	20	21	20	20	19	21	20.50
	2025-2030	Tour 2	19	20	21	23	21	22	19	20	17	21	20	19	20.17
	0025-0030	Tour 3	17	19	18	20	18	21	22	19	20	20	19	22	19.58

**DATE: 6/19/2008**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	17	19	20	17	24	20	18	23	20	19	24	17	19.83
	1200-1205	Tour 2	22	17	24	20	19	22	20	17	18	23	20	24	20.50
	1500-1505	Tour 3	20	17	22	19	24	23	17	19	23	21	17	20	20.17
5th FLOOR	0910-0915	Tour 1	18	24	17	19	22	24	21	17	21	19	23	24	20.83
	1210-1215	Tour 2	22	19	24	18	22	17	20	24	19	24	17	19	20.42
	1510-1515	Tour 3	20	18	17	20	19	20	17	24	17	18	23	20	19.42
ROOF PERIMETER	0925-0930	Tour 1	18	22	20	17	19	23	20	19	17	21	18	22	19.87
	1225-1230	Tour 2	23	20	17	21	24	18	23	17	22	18	20	21	20.33
	1525-1530	Tour 3	17	18	24	20	23	17	20	17	23	18	22	23	20.17

**DATE: 6/19/2008 2nd SHIFT**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	1700-1705	Tour 1	21	22	24	20	23	19	22	25	21	22	20	23	21.83
	2000-2005	Tour 2	18	21	20	23	20	18	21	20	23	22	24	21	21.08
	0000-0005	Tour 3	20	22	21	24	20	21	19	19	21	22	21	23	21.08
5th FLOOR	1710-1715	Tour 1	25	21	24	23	20	22	23	25	22	19	20	21	22.08
	2010-2015	Tour 2	20	22	23	20	18	19	21	20	19	21	22	20	20.42
	0010-0015	Tour 3	21	22	21	24	18	22	21	23	21	23	20	21	21.42
ROOF PERIMETER	1725-1730	Tour 1	23	22	23	25	22	23	25	21	23	24	22	20	22.75
	2025-2030	Tour 2	20	17	22	18	19	20	21	23	22	20	21	20	20.25
	0025-0030	Tour 3	20	18	19	23	22	21	23	17	20	18	21	22	20.33

**DATE: 6/20/2008**

AREA:	TIME:	Tour #:	TOUR AVERAGE:												
PERIMETER OF BUILDING	0900-0905	Tour 1	17	22	20	18	24	17	21	19	17	23	24	18	20.00
	1200-1205	Tour 2	19	23	24	19	21	19	23	20	18	22	19	20	20.58
	1500-1505	Tour 3	21	24	17	19	22	20	17	19	23	20	19	23	20.33
5th FLOOR	0910-0915	Tour 1	19	24	20	17	23	18	20	20	17	22	21	19	20.00
	1210-1215	Tour 2	24	20	18	23	19	22	17	23	17	19	24	20	20.50
	1510-1515	Tour 3	22	19	23	20	18	22	24	17	23	19	20	22	20.75
ROOF PERIMETER	0925-0930	Tour 1	17	19	24	20	19	23	17	20	18	23	19	23	20.08
	1225-1230	Tour 2	19	20	17	22	17	21	24	18	22	20	18	23	20.08
	1525-1530	Tour 3	20	19	22	17	23	20	21	17	19	22	20	17	19.75

**DATE: 6/20/2008 2**



Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Work Shift/Project Phase	Sample Volume (m <sup>3</sup> )	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Silica-Quartz Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											10				
EPA Site Specific Trigger Levels											10				
EMSL	FH-061608-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/16/2008	Remediation	2.882	040814833-0001	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/23/2008	No	No	
EMSL	FH-061608-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/16/2008	Remediation	2.888	040814833-0002	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/23/2008	No	No	
EMSL	FH-061608-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/16/2008	Remediation	2.886	040814833-0003	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/23/2008	No	No	
EMSL	FH-061608-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/16/2008	Remediation	2.886	040814833-0004	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/23/2008	No	No	
EMSL	FH-061608-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/16/2008	Remediation	2.886	040814833-0005	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/23/2008	No	No	
EMSL	FH-061608-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/16/2008	Remediation	2.886	040814833-0006	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061608-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/16/2008	Remediation	2.886	040814833-0007	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061608-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/16/2008	Remediation	2.886	040814833-0008	06/18/2008	06/21/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/23/2008	No	No	
EMSL	FH-061708-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/17/2008	Remediation	2.878	040815044-0001	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/17/2008	Remediation	2.880	040815044-0002	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/17/2008	Remediation	2.882	040815044-0003	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/17/2008	Remediation	2.882	040815044-0004	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/17/2008	Remediation	2.880	040815044-0005	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/17/2008	Remediation	2.880	040815044-0006	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/17/2008	Remediation	2.882	040815044-0007	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/23/2008	No	No	
EMSL	FH-061708-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/17/2008	Remediation	2.880	040815044-0008	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061708-68	DUPLICATE (STATION #1)	06/17/2008	Remediation	2.878	040815044-0010	06/19/2008	06/22/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/23/2008	No	No	
EMSL	FH-061808-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/18/2008	Remediation	2.884	040815102-0001	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/24/2008	No	No	
EMSL	FH-061808-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/18/2008	Remediation	2.878	040815102-0002	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/24/2008	No	No	
EMSL	FH-061808-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/18/2008	Remediation	2.880	040815102-0003	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/24/2008	No	No	
EMSL	FH-061808-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/18/2008	Remediation	2.880	040815102-0004	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/24/2008	No	No	
EMSL	FH-061808-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/18/2008	Remediation	2.880	040815102-0005	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/24/2008	No	No	
EMSL	FH-061808-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/18/2008	Remediation	2.880	040815102-0006	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/24/2008	No	No	
EMSL	FH-061808-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/18/2008	Remediation	2.880	040815102-0007	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/24/2008	No	No	
EMSL	FH-061808-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/18/2008	Remediation	2.880	040815102-0008	06/20/2008	06/24/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/24/2008	No	No	
EMSL	FH-061908-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/19/2008	Remediation	2.884	040815243-0001	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/25/2008	No	No	
EMSL	FH-061908-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/19/2008	Remediation	2.884	040815243-0002	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/25/2008	No	No	
EMSL	FH-061908-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/19/2008	Remediation	2.884	040815243-0003	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/25/2008	No	No	
EMSL	FH-061908-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/19/2008	Remediation	2.882	040815243-0004	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/25/2008	No	No	
EMSL	FH-061908-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/19/2008	Remediation	2.882	040815243-0005	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/25/2008	No	No	
EMSL	FH-061908-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/19/2008	Remediation	2.882	040815243-0006	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/25/2008	No	No	
EMSL	FH-061908-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/19/2008	Remediation	2.840	040815243-0007	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/25/2008	No	No	
EMSL	FH-061908-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/19/2008	Remediation	2.880	040815243-0008	06/20/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/25/2008	No	No	
EMSL	FH-062008-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/20/2008	Remediation	2.882	040815364-0001	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062008-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/20/2008	Remediation	2.882	040815364-0002	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062008-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/20/2008	Remediation	2.882	040815364-0003	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062008-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/20/2008	Remediation	2.884	040815364-0004	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/26/2008	No	No	
EMSL	FH-062008-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/20/2008	Remediation	2.884	040815364-0005	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	4	06/26/2008	No	No	
EMSL	FH-062008-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/20/2008	Remediation	2.884	040815364-0006	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062008-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/20/2008	Remediation	2.882	040815364-0007	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062008-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/20/2008	Remediation	2.882	040815364-0008	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/26/2008	No	No	
EMSL	FH-062108-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/21/2008	Remediation	2.882	040815366-0001	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062108-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/21/2008	Remediation	2.872	040815366-0002	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062108-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/21/2008	Remediation	2.872	040815366-0003	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062108-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/21/2008	Remediation	2.872	040815366-0004	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/26/2008	No	No	
EMSL	FH-062108-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/21/2008	Remediation	2.882	040815366-0005	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062108-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/21/2008	Remediation	2.882	040815366-0006	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062108-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/21/2008	Remediation	2.872	040815366-0007	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062108-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/21/2008	Remediation	2.882	040815366-0008	06/23/2008	06/25/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062208-29	#1 - SIDEWALK BRIDGE LEVEL NW CORNER	06/22/2008	Remediation	2.884	040815365-0001	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	2	06/26/2008	No	No	
EMSL	FH-062208-30	#2 - SIDEWALK BRIDGE LEVEL SW CORNER	06/22/2008	Remediation	2.894	040815365-0002	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062208-31	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	06/22/2008	Remediation	2.894	040815365-0003	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/26/2008	No	No	See Note 1
EMSL	FH-062208-32	#4 - SIDEWALK BRIDGE LEVEL NE CORNER	06/22/2008	Remediation	2.894	040815365-0004	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062208-33	#5 - 5TH FL SETBACK ROOF N. SIDE	06/22/2008	Remediation	2.884	040815365-0005	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	
EMSL	FH-062208-34	#6 - 5TH FL SETBACK ROOF SW SIDE	06/22/2008	Remediation	2.884	040815365-0006	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	<7	06/26/2008	No	No	See Note 1
EMSL	FH-062208-35	#7 - 5TH FL SCAFFOLD AT SE CORNER	06/22/2008	Remediation	2.894	040815365-0007	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	<2	06/26/2008	No	No	
EMSL	FH-062208-36	#8 - 5TH FL SCAFFOLD AT NE CORNER	06/22/2008	Remediation	2.886	040815365-0008	06/23/2008	06/26/2008	NIOSH 7500 XRD	Silica-Quartz	3	06/26/2008	No	No	

Note 1: Secondary quartz peak used for sample due to suspected primary peak interference.

**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m <sup>3</sup> )	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	Dioxin/Furans Concentration (ng/m <sup>3</sup> )	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
Target Air Quality Levels											0.00025				
EPA Site Specific Trigger Levels											0.025				
STL-SAC	FH-061908-40	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210175003	06/21/2008	06/29/2008	TO-9	Toxicity Equivalent Quotient (TEQ)	0.000033	07/07/2008	No	No	

**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m <sup>3</sup> )	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	PAHs Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
<b>Target Air Quality Levels</b>											0.034				
<b>EPA Site Specific Trigger Levels</b>											3.4				
STL-SAC	FH-061908-49	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210181003	06/21/2008	06/29/2008	8270C SIM	BAP-equivalent	<0.007	07/07/2008	No	No	

**Submittal Summary - Remediation Phase Week 60 (06/16/08 to 06/22/08)**

Lab Name	Airtek Field Sample No.	Sample Location	Collection Start Date	Project Phase	Sample Volume (m <sup>3</sup> )	Lab Sample ID	Date Received	Date Analyzed	Analytical Method	Parameter Name	PCBs Concentration (ug/m3)	Date Reported	Exceeds Target Air Quality Levels?	Exceeds EPA Site Specific Trigger Levels?	Comments
<b>Target Air Quality Levels</b>											<b>0.12</b>				
<b>EPA Site Specific Trigger Levels</b>											<b>12</b>				
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1016	<0.0021	07/07/2008	No	No	
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1221	<0.0021	07/07/2008	No	No	
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1232	<0.0021	07/07/2008	No	No	
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1242	<0.0021	07/07/2008	No	No	
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1248	<0.0021	07/07/2008	No	No	
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1254	<0.0021	07/07/2008	No	No	
STL-SAC	FH-061908-58	#3 - SIDEWALK BRIDGE LEVEL SE CORNER	6/19/2008	Remediation	360	G8F210172003	06/21/2008	07/02/2008	TO-4	Aroclor 1260	<0.0021	07/07/2008	No	No	